

Intruder Alarm Servicing Worksheet

Keybury Fire & Security Units 4 & 5 Worth Enterprise Park, Valley Road, Keighley, West Yorkshire

BD21 4LN **Tel:** 01535 661197

Client and Jol	b Details								
Contract	J2885			Job Number	-791863				
Client	Viamed Ltd Rf			Call Type	Routine Maintenance				
15 Station Road				Appointment Date/Time	17/08/23 13:30				
	Cross Hills			Reported Reason For Call					
	West Yorkshire			PM ANNUAL					
				2 SPACES					
	BD20 7DT				ted zone 36 conservatory dueltech at cus				
Contact	Sir/Madam				d system amd conservatory fed kitchen p	ir zon			
Telephone	01535 634542			e 35 so thereis now a live id l	line in trunking externally				
email	helen.lamb@viamed.co	o.uk							
System Detail									
System Detail									
System Type	Intruder Alarm BS4737	Pt 1, 3		STU	B013P2DP3F				
Panel Type	EURO 1/28+			Software version					
Signal Type 2 x ATS Radio/Radio			Installed						
Chip DW030012				System test with ARC					
ARC	CUSTODIAN			Inform customer alarm on test					
Inspection									
Equipment as p	er specification	þ	Log of un-setting OK	þ	If not, why				
All cables undamaged			Entry procedure OK	b	-				
Is equipment firmly fixed			Exit procedure OK	þ					
Is equipment clean			Live system sets OK	þ	Adverse effects on system due to				
Is the range un-obstructed			Live system un-sets C	DK þ	environmental conditions (If any)				
Is the range un-obstructed Log of setting OK				•					
Service Checl	ks								
Batteries Tested	d	þ	Contacts Checked 5		Circuit Resistance Tested	þ			
Circuit wiring tested			PA Buttons Tested		Movement detectors Tested	þ			
Glass protection examined			Have any items been disconnected? Other devices tested?						
Audible warning test			Cities devices tested ?						
Remote signal test									
CMC Confirmati		þ							
Check Contro	ls and PSU								
		þ	D-44 1144	ı la	Bettery mA clarm (Ne mains)	0.00			
All fuses correctly fitted			Battery pass load test Battery take over - mains disconnect		Battery mA alarm (No mains)	0.89			
Check for earth			1 ,	Zone attributs as per specification	þ				
Battery free from corrosion			Charge Rate (Volts DC) All zones tamper zones			þ			
Battery date & under 4yrs old			Battery voltage after 1						
Battery charging voltage 13.67V Battery mA standby (No mains) 0.16									
Check Signall	ling								
Line fault at par	nel	þ	How many ATS paths	1	ATS Comments				
			Does each path operate correctly						
•		þ	Inspect for potential p						
Close Down				,					
			اما	0		la			
Historical log u			р	System free from false alarms System date/time correct					
Causes of false alarms eliminated			þ	System date/time correct					
Number of zones left on test			Removed all tamper/remote links		р р				
Reset the syste	m		р	System off test with ARC		р			
Customer Rep	oort								
Engineers finding				Work To be Completed					
Annual service of ir	ntruder alarm system. All po	oints tested Ok	ζ.	,					
				Further Action Required by Customer					
				ruriner Action Required by Customer					
System left wor	kina	h							
System left working Signal strength Suitable? Not T				Further visit required+when					
J									

Customer signature confirming renewal of maintenance contract (ONLY FOR ANNUAL SERVICES)
Cathy



Intruder Alarm Servicing Worksheet

Keybury Fire & Security
Units 4 & 5 Worth Enterprise Park, Valley
Road,
Keighley, West Yorkshire
BD21 4LN
Tel: 01535 661197

Timesheets Date on Site	Arrival	Departure	Customer Name / Signature	Engineers Name / Signature
17/08/2023	09:22:00	15:09:00	Cathy	AB Stacey Wood