

DL Full, HL Full



✓CID4348 Opera 00007282 Type:Company Supplier Customer
Honeywell Healthcare Solutions GmbH Alter Holzhafen 18, Wismar,
D-23966, Germany

Tel 0049 3841 360204 Euro Distributor (0004)

VAT DE137437213

Account Home	Main Details	Account Memos	Sales History	Purchase Orders	Supplier Returns	Stock References	Cust./Supp. Returns	Service Visits
Distributor Agreements	Documents Files	Linked Issues	Regulatory Agreements					

MHRA Registration number: 29372

BOX:937

Manufacturer RMA : 300267904

☒ Repaired ☐ No Fault Found

Review	Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
Last Rev Sep 23 8010006 Customer Stats	8010006		2082979	210146794	Low Output Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2095772	211147502	No Output Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2095787	211147517	No Output Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2137092	212147955	High Output Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2166284	302149093	No Output Country of Origin: Germany	☐	☐	☐	☒	☐	☐	

				Customs value only: 5.00 euro								
Last Rev Sep 23 8010006 Customer Stats	8010006		2249034	306150771	No Output Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2275242	307151675	Output changes under pressure Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2280956	307151778	Output changes under pressure / Unstable Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2284770	308152035	Output changes under pressure Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	
Last Rev Sep 23 8010006 Customer Stats	8010006		2284907	308152172	Output changes under pressure Country of Origin: Germany Customs value only: 5.00 euro	☐	☐	☐	☒	☐	☐	

Update Returns

Customer Failure Statistics

Start From 28/09/2021 End at 28/09/2023

Invoice Correction 5264791686

ORIGINAL

Invoice Correction Date: 22.09.2023

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100937

23966 Wismar

Germany

Sold to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Sold to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

Order Information:
Credit Memo Request: 64137894
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date

Ship to: 1797448
Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00010	E1002733 Oxygen Sensor OOD103 VAN 8010006 Customer Part Nbr: 8010006	10	EA	21,74	-217,40	0%

credit note for SN:

146794 ✓
147502 ✓
147517 ✓
147955 ✓
149093 ✓
150771 ✓
151675 ✓
151778 ✓
152035 ✓
152172 ✓

Totals

Total Before VAT	-217,40 EUR
VAT-Total	0,00 EUR
Total Amount	-217,40 EUR

Tax Information

Tax Exempt Reason:	Tax free export - Goods
Fulfilment Date:	22.09.2023

Invoice #:

Bank Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

IBAN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Unless otherwise agreed in writing by the parties, all sales of products and/or services in this document shall be governed solely by the applicable Honeywell Terms and Conditions in effect at the time a Purchase Order is accepted by Honeywell, a copy of which can be found at <https://sps.honeywell.com/us/en/support/safety/legal-documents/sst>. Honeywell's acknowledgment of receipt of a Purchase Order shall not constitute acceptance. By continuing with this transaction, you (Buyer) agree to those Honeywell Terms and Conditions, which are subject to change at Honeywell's discretion without notice. Honeywell expressly limits its acceptance, fulfillment and performance of this Purchase Order to the terms in the Honeywell Terms and Conditions and expressly rejects any different, conflicting or additional terms in the Purchase Order or any other Buyer documents. This sale shall be governed by the Terms and Conditions of the Honeywell legal entity listed on this document.

PRÜFBERICHT – TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD

ENVITEC
by Honeywell

Kunde/ Customer	Vandagaph	Retour/ RMA- No.	Kunde/Customer P75 3100937	EnviteC 300267904
Artikel/ Article	000103	Anzahl/ Quantity	10	Eing.Datum/ Inc.Date 20.09.23
Bearbeitet/ processed	K. Bue	Prüfdatum/ Insp. Date	21.09.23	Geprüft/ Inspected Bue

Produkt/ Identification			Messwert/ Test Result				Bewertung/ Evaluation			
Nr.	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found	Fehlercode/ Failure- code	Austausch / Replacement
1	146794	10122	0						4	
2	147502	11122	0						4	
3	147517	11122	0						4	
4	147855	12122	0						4	
5	149093	02123	10,2	1001	fehlerhaft				3	
6	150771	06123	13,8	40	i.o.				1	
7	151675	07123	11,4	85	i.o.			X		
8	151778	07123	48,4	279	fehlerhaft				1:3	
9	152035	08123	11,6	38	i.o.			X		
10	152172	08123	11,6	37	fehlerhaft				2	
11										
12										
13										
14										
15										
16										
17										
18										
19										
20										

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance

Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance

Fehler O2-S005: Gehäuse defekt/ Housing defective

Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable

Fehler O2-S004: Signal 0mV / Signal 0mV

Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage