



Hunter and Co

 **CID3540** Opera **00020062** Type:**Automotive Company Distributor UK**
Hunter and Co Garage Equipment Services, Duckhill Farm House, Inzievar By Cairneyhill,
 Dunfermline, Fife, KY12 8HB, Scotland
 Tel **01383852049** GBP Distributor (0002) [Log Call](#) [Add Issue](#)
 Credit 30 Days after date of invoice Credit Limit 0.00GBP

 Log Call

Add Issue

Credit 30 Days after date of invoice Credit Limit 0.00GBP

Account
Home

 Main Details

Account Memos

 Sales History

Stock References

[Cust./Supp. Returns](#)

Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68592

SRS Created : 04 Oct 2023
Created By Robert Connor
Add Watch

[Print Barcodes](#)[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68592		Notes
SELECT * FROM viamedquoteaddress where ID='3540'		04/Oct/2023 Robert Connor
Company / Hospital	Hunter and Co	04/Oct/2023 Robert Connor
Contact Name	Janice Hunter	Returned 1 x R-22A s/n 931337, originally invoiced to Envirogen.
Department	Accounts	11/Oct/2023 Steve Hardaker
Position		Advise them that this sensor wasn't one that we supplied to them, their customer may have sent it to them in error. Will return unreplaced.
Company Phone	01383852049	12/Oct/2023 Sophie Lines
Direct Phone	01383852049	Janice called and would like the sensor returning directly to their customer:
Opera Account	00020062	FAO: William Burnett Arnold Clark Garage Equipment 151 Kilbirnie Street
Email	hunterandco@outlook.com	Glasgow G5 8JH
Order Number		12/Oct/2023 Catherine Spence
Viamed ORD Number		Warranty removed as not sold to Hunter. Requested to return un replaced
Date Received Into building	04 Oct 2023	back to their customer, for them to send back to the supplier that they purchased it from.
Issues?	308586 309253 309254	
		LINKED ISSUE NOTES:
		308586:
		AutoGenerated Issue SRS68592 Appears to be Complete
		09 Oct 2023 Catherine Spence
		noted, issue with repair waiting for SN to come back off leave
		309253:
		AutoGenerated Issue SRS68592 Appears to be Complete

309254:

AutoGenerated Issue SRS68592 Appears to be Complete

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36059	Oxygen Sensor	0110122 Requires Service Manual Linking in System	 2192465	931337	Oxygen Sensor R-22A	No	No	Return Unrepaired 12 Oct 2023 Catherine Spence	Non Linear	00:00
SRN36059 Engineer Notes: INTERNAL NOTES not for customer discussion 05/Oct/2023 Philip Crossley 9.2 in air and 44.7 in oxygen. This sensor is nonlinear. Replaced under warranty with S/N 984876 12/Oct/2023 Catherine Spence Returned un replaced back to their customer as requested by Hunter as this sensor was not sold to hunter, so they dont have any warranty on it.										
SRN36059	Output mV					9.2				
SRN36059	Linearity out of tolerance					Selected				

Currently Viewing ITEM SRN36059 Oxygen Sensor 0110122 931337 Oxygen Sensor R-22A

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	05/Oct/2023 Philip Crossley 9.2 in air and 44.7 in oxygen. This sensor is nonlinear. Replaced under warranty with S/N 984876 12/Oct/2023 Catherine Spence Returned un replaced back to their customer as requested by Hunter as this sensor was not sold to hunter, so they dont have any warranty on it.	Non added Yet

0110122 984876 2304273

▲