











Honeywell Healthcare Solutions GmbH

✓CID4348 Opera 00007282 Type:Company Supplier Customer
Honeywell Healthcare Solutions GmbH Alter Holzhaufen 18, Wismar,
, D-23966, Germany

Tel 0049 3841 360204 Euro Distributor (0004) 

Add Issue

VAT DE137437213


 Account Home	 Main Details	 Account Memos	 Sales History	 Purchase Orders	 Supplier Returns	 Stock References	 Cust/Supp. Returns	 Service Visits
 Distributor Agreements	 Documents Files	 Linked Issues	 Regulatory Agreements					

MHRA Registration number: 29372

BOX:938








Manufacturer RMA : 300268059

☒ Repaired ☐ No Fault Found



[Close File 938](#)

Tick All Replaced

Review	Stock Ref	Sup Ref	B/C	S/N	Fault	Replaced	No Fault Found	Repaired	Credited	Out Warranty	Returned Unrepaired	Notes
	 8010004		2054956	JJ139719	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	waiting on rel times cg 18/11
	 8010004		2099632	JJ141447	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
	 8010004		2135231	JJ142128	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
	 8010004		2135238	JJ142135	No Output Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
	 8010004		2135272	JJ142169	Unstable Output Signal Country of origin: Germany	☐	☐	☐	☒	☐	☐	

				Custom value: 5.00 euro								
Review 8010004 Customer Stats	8010004		2151216	JJ142740	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2157596	JJ142890	No Output Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2157627	JJ142921	Low Output Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2157633	JJ142927	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2165017	JJ143586	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2179257	JJ143939	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2187201	JJ144245	High Output Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2206993	JJ144840	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2209597	JJ145064	Unstable Output Signal	☐	☐	☐	☒	☐	☐	

					Country of origin: Germany Custom value: 5.00 euro							
Review 8010004 Customer Stats	8010004		2209627	JJ145094	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010004 Customer Stats	8010004		2255887	JJ146016	Unstable Output Signal Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	
Review 8010007 Customer Stats	8010007		2189864	S01117608	Erratic Country of origin: Germany Custom value: 5.00 euro	☐	☐	☐	☒	☐	☐	

Update Returns

Customer Failure Statistics

Start From 20/10/2021 End at 20/10/2023

SRS 68571
SRS 68577

Requested 21-9-23
by email cg

Viamed Request Manufacturer Returns Number

Delivery Address:

Honeywell Healthcare Solutions GmbH

Andre Schliemann

Alter Holzhafen 18

Date: 19 Sep 2023

RMA: REQUESTED

Viamed Ref: RTS100938

RMA 300268059

Shipper Address:

Viamed Ltd.

15 Station Road

Crosshills

Keighley

West Yorkshire

BD20 7DT

Tel: +44 (0) 1535 6345

Fax: +44 (0) 1535 6355

Email: info@viamed.co

D-23966

See Attached Listing for Serial numbers and Faults

80E.

Part Number

Viamed Part Number

Description

Quantity

8010004

8010004

Oxygen Sensor - R17JJ-CCR

16

8010007

8010007

Oxygen Sensor - NaNS01

1

+29

12A847290454956024

cg 22-9-23

Invoice Correction 5264934904**ORIGINAL**

Invoice Correction Date: 06.10.2023

Honeywell Healthcare Solutions GmbH

Alter Holzhafen 18

Purchase Order No: RTS3100938

23966 Wismar

Germany

Billed to: 1797448Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom**Sold to:** 1797448Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom**Order Information:**Credit Memo Request: 64145333
Sales Office: 2170 DE SPS Wismar
Incoterms: FCA Origin
Payment Terms: Net 30 Days After Invoice Date**Ship to:** 1797448Vandagraph Sensor Technologies Ltd.
15 Station Road
Cross Hills, West Yorkshire
KEIGHLEY
BD20 7DT
United Kingdom

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00010	E1001581 Oxygen Sensor OOD103-1V Customer Part Nbr: 8010007 Credit note for SN: 117608	1	EA	22,65	-22,65	0%

Invoice #:

Link Details: No Payment Due

Account Name:

Account No:

Bank Key:

Swift Code:

AN:

Payment method:

Registered No: Schwerin HRB 1838

VAT Reg No: DE137437213

Federal ID #:

Registered Address: Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany

Credit Analyst: Xenia Musat

Sales Rep: Stefan Dreyer

Customer Care Rep: Jessica Wagner +49 3841 360 206

Unless otherwise agreed in writing by the parties, all sales of products and/or services in this document shall be governed solely by the applicable Honeywell Terms and Conditions in effect at the time a Purchase Order is accepted by Honeywell, a copy of which can be found at <https://sps.honeywell.com/us/en/support/safety/legal-documents/sst>. Honeywell's acknowledgment of receipt of a Purchase Order shall not constitute acceptance. By continuing with this transaction, you (Buyer) agree to those Honeywell Terms and Conditions, which are subject to change at Honeywell's discretion without notice. Honeywell expressly limits its acceptance, fulfillment and performance of this Purchase Order to the terms in the Honeywell Terms and Conditions and expressly rejects any different, conflicting or additional terms in the Purchase Order or any other Buyer documents. This sale shall be governed by the Terms and Conditions of the Honeywell legal entity listed on this document.

ORIGINAL

Invoice Correction 5264934904

Invoice Correction Date: 06.10.2023

Honeywell Healthcare Solutions GmbH
Alter Holzhafen 18
23966 Wismar
Germany

Purchase Order No: RTS3100938

EM NO.	Material No.	QTY	UOM	UNIT PRICE	EXT. PRICE	VAT %
00020	E1001721	16	EA	31,14	-498,24	0%
	Oxygen Sensor OOD103-2V					
	Customer Part Nbr: 8010004					
	Credit note for SN:					
	139719					
	141447					
	142128					
	142135					
	142169					
	142740					
	142890					
	142921					
	142927					
	143586					
	143939					
	144245					
	144840					
	145064					
	145094					
	146016					

Totals

Total Before VAT	-520,89 EUR
VAT-Total	0,00 EUR
Total Amount	-520,89 EUR

Tax Information

Tax Exempt Reason:	Tax free export - Goods
Fulfilment Date:	06.10.2023

Integrity and Compliance at Honeywell

Honeywell places the highest value on the integrity of its business operations. We expect our employees and business partners to comply with our Code of Business Conduct and all applicable laws and regulations. If you become aware of illegal or improper conduct by a Honeywell employee please contact your Honeywell relationship manager. You can also report misconduct directly to us either via e-mail to our Integrity and Compliance Office at access.integrity.helpline@honeywell.com or via our Access helpline accessible worldwide at 800-237-5982.

Ins #:

Registered No:	Schwerin HRB 1838	VAT Reg No:	DE137437213	Federal ID #:
Registered Address:	Honeywell Healthcare Solutions GmbH, Alter Holzhafen 18, Wismar, 23966, Germany			

PRÜFBERICHT - TEST REPORT

Sauerstoffsensoren/Oxygen Sensors OOA, OOI, OOD

Kunde/ Customer	Vandagrap	Retour/ RMA- No.	Kunde/Customer	Envitec	300268 059
Artikel/ Article	000103-1V 000103-2V	Anzahl/ Quantity	116	Eing.Datum/ Inc.Date	
Bearbeitet/ processed	K. B. M.	Prüfdatum/ Insp. Date	04.10.23	Geprüft/ Inspected	B. M.

Produkt/ Identification		Messwert/ Test Result				Bewertung/ Evaluation				
Nr.	Seriennummer/ Serial no.	Lieferlos/ Manufact. code	Luftwert/ Air signal @ 20,9% O ₂ [mV]	Nullsignal/ Offset @ 0% O ₂ [µV]	Linearität/ Linearity [%]	Bemerkung/ Remark	außerhalb Garantie/ out of warranty	kein Fehler festgestellt/ no failure found	Fehlercode/ Failure- code	Austausch / Replacement
1	139719	08122	11.1	29	i.o.					
2	141447	11122	11.2	32	i.o.	Blase			7	
3	142128	12122	11.4	30	i.o.					
4	142135	12122	0						4	
5	142169	12122	11.3	18	i.o.					
6	142740	01123	10.8	29	i.o.					
7	142890	01123	0						4	
8	142921	01123	10.2	1157	fehlerhaft				3	
9	142927	01123	11.0	26	i.o.					
10	143586	02123	11.1	28	i.o.					
11	143939	03123	12.5	29	i.o.	Blase			7	
12	144245	04123	21.6	60	i.o.	NTC geraden			1	
13	144840	04123	11.5	32	i.o.					
14	145064	04123	11.7	34	i.o.	Blase			7	
15	145094	04123	11.1	32	fehlerhaft	Blase			2	
16	146016	07123	11.1	34	i.o.					
17	147608	03123	10.6	30	i.o.					
18										
19										
20										

Fehler O2-S001: Luftwert außerhalb Toleranz/ Air signal out of tolerance

Fehler O2-S003: Offset außerhalb Toleranz/ Offset out of tolerance

Fehler O2-S005: Gehäuse defekt/ Housing defective

Fehler O2-S007: Sonstiges (unter Angabe in Bemerkung) / Others (see remark)

Fehler O2-S002: Signal instabil / Signal not stable

Fehler O2-S004: Signal 0mV / Signal 0mV

Fehler O2-S006: Elektrolyt Austritt / Electrolyte leakage

X PPS 13 Polyvis