Service Repair Sheet SRS68609

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mark Brucks

Tenacore LLC

Supply Chain Director

8002972241

7146176757

00007996

mark.brucks@tenacore.com

23/Oct/2023

Robert Connor

Viamed

Quote

Goods In Only
Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer
Signed:
Date:

Goods Out Only
Cleaned by Viamed before
returning to customer
Signed:
Date:
Date:

VIAMEDclean

Notes 19/Oct/2023 Kate Griffiths 19/Oct/2023 Kate Griffiths

Will send in V1000 for calibration, s/n PR02976A11. PO PR02976A11 received (proforma customer)

23/Oct/2023 Robert Connor

Received 1 x V1000 s/n PR02976A11, with 8 x AA battery and grey plastic carry case.

Ready For quote

Repair Complete Signed

Careen 30-10.23

acceen 9.11.23

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|------------------|-----------|---------------|----------|
| SRN36105 | Foetal Simulator | 1410000 | PR02976A11 | 2 |

14800000 × 1 @ \$63.40 S/N, SRS, SRN

1430309 x 1 fcc & Add to Order

UPS X 1 1.20kg 32x24x1200 Post of services + cost of services +

NO carrag

TENACORE.

Purchase Order

#PO3539

Tenacore LLC 3115 Airway Ave. Costa Mesa CA 92626 **United States**

RMA # SRS 68609

10/18/2023

Vendor

Viamed United States Ship To

Tenacore LLC 3115 Airway Ave. Costa Mesa CA 92626 **United States**

\$63.40

Receive By:

Receive By

Terms

Net 30

Quantity Item Description

Vendor Item

Unit Price

Ext Price

TESTEQUIPMENTCALIBRATION

Viamed V1000 Calibration SN PR02976A11

\$63.40

\$63.40

Total

\$63.40

THE SPECIFICATIONS, INCLUDING THE MATERIALS AND PROCESSES INVOLVED THERE IN, ARE AN ESSENTIAL TERM OF THIS PURCHASE ORDER, SUPPLIER SHALL NOT CHANGE ANY OF SUCH SPECIFICATIONS, MATERIALS, OR PROCESSES WITHOUT GIVEN WRITTEN NOTICE OF SUCH PROPOSED CHANGE TO TENACORE'S PRODUCTS OR SERVICE, AND WITHOUT RECEIVING TENACORE'S WRITTEN APPROVAL OF SUCH PROPOSED CHANGES.

Service Repair Sheet 68609

Contact Name

Company/ Hospital Name

Position

Direct Phone General Phone

Opera Account

Email

Order Number Date Received

Booked in By

Mark Brucks

Tenacore LLC

Supply Chain Director

8002972241

7146176757

00007996

mark.brucks@tenacore.com

Paid proforma 23/Oct/2023

Robert Connor

Repair

SRN36105

Ref

S/N

Equipment Type

1410000 PR02976A11

Foetal Simulator

Complete - Repaired Time:0 Hour(s)

Parts Replaced

Qty: 1

1480000

V1000 has had transducer interface cushion replaced and calibration has been checked