Service Repair Sheet SRS68607

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Tim Bray

Medisafe Ltd

01962 886214

01962885777

00011608

tim.bray@medisafe.org.uk

19/Oct/2023

Robert Connor

Viamed

Quote

Notes 18/Oct/2023 Kate Griffiths 18/Oct/2023 Kate Griffiths Faulty V1000, Tim does not know the fau

Faulty V1000, Tim does not know the fault. s/n: PR0490A19

19/Oct/2023 Robert Connor

Received 1 x V1000 s/n PR0490A19, with 4 x AA battery and hard plastic case.

Ready For quote

Repair Complete Signed

Careen 30.10.23

C9200 10.11.23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36100	Foetal Simulator			N

1440000 × 1 2 E90 SIN, SRS, SRN 1430300 × 1 2 E95 SRS, SRN 1430288 × 1 2 E4-80 SRS, SRN SRS, SRN OPS + 12 E12. VIAMEDCLEAR
Goods In Only
Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer
Signed:
Date:

Goods Out Only
Cleaned by Viamed before
returning to customer
Signed:
Date:
Date:

Service Repair Sheet 68607

Contact Name

Company/ Hospital Name

Direct Phone General Phone

Opera Account

Email

Order Number

Date Received Booked in By Tim Bray

Medisafe Ltd

01962 886214 01962885777

00011608

tim.bray@medisafe.org.uk

5774

19/Oct/2023

Robert Connor

Repair

SRN36100

Ref

S/N

Equipment Type

1410000 PR0490A19

Foetal Simulator

Complete - Repaired Time :1 Hour(s)

Parts Replaced

Qty: 1

1430300

Qty: 1

1430288

Qty: 1

1440000

I have replaced the battery contacts and pcb. There has been a lot of corrosion from a previous battery leak so I have also replaced all the case screws and scrubbed the case clean internally.

V1000 has also had the transducer interface cushion replaced and calibration has been checked.



PURCHASE ORDER

TO:

Viamed Limited 15 Station Road **Cross Hills Keighley** West Yorkshire

BD20 7DT

Tel:

Fax:

01535 634542 01535 635582

Please deliver to:

Medisafe Ltd

Medisafe

Unit 7 Ringtower Centre Moorside Road, Winnall

Winchester Hampshire

SO23 7RZ

Purchase Order Number: 5774

Purchase Order Date:

18 Oct 2023

Customer Order No:

Repairs Team SRS68607

QUANTITY	MODEL NO	DESCRIPTION	PART NO.	COST	SUBTOTAL
		V1000 Simulator PRO49OA19			
		for repair			
1		1440000 Labour Charge		£90.00	£90.00
1		1430300 V1000 Assembly		£95.00	£95.00
1		1430288 V1000 Battery Clip Set		£4.80	£4.80
1		PPOPS1 UPS Courier Delivery -		£12.00	£12.00
		Standard			
		SUBTOTAL:		£201.80	
				CARRIAGE:	£0.00
			VAT @	20.0%	£40.36
				TOTAL:	£242.16