

Symbols – Oxygen Sensor Bag Label



Manufactured date symbol (factory) and manufactured date format (year—month) in line with EN standards.



'Consult instructions for use' symbol – to instruct the users to read the OEM's operating manual/s.



The letters CE are the abbreviation of the French phrase Conformité Européenne (European Conformity). CE marking on the product is manufacturer's declaration that the product complies with the essential requirements of the relevant European health, safety and environmental protection legislation - in practice by the associated product directives. The product directives contain the essential requirements and/or performance levels; and harmonized standards to which the product must conform.



Serial number and bar code - standard format .


We can accommodate specific serial number formats.



Caustic warning symbol, in accordance with international regulations.



Specific 'harmful' symbol, in accordance with international regulations. In this case specifically relates to lead (Pb).



Storage symbol – cautions/covers against extreme storage conditions.

The standard format label has supplementary information:

- i) Extra text added to warn about possible sensor leakages...
- ii) Caution regarding puncturing the sensor bag...
- iii) Caution added stating that the sensor requires time to stabilize after installation.

Should there currently not be any reference in OEMs' manuals regarding this matter, then this extra note may avoid possible future user misunderstandings.