

Service Repair Sheet SRS68688

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Mr Mahesha
BDI India Private Limited
Customer Support
Customer Support

919108918492
00006454
mahesha@bdi-india.com

12/Feb/2024
Robert Connor
Viamed
Quote

Notes Sending in 10 x V1000 s/n as follows: PR02380A12PR02529A11PR02529A14PR02529A15PR02529A17PR02529A18PR02529A20PR02529A22PR02540A13PR02540A14Will mention they need to be sent in clean in my reply and will ask if calib only for serv/calib

05/Feb/2024 Kate Griffiths

Sending in 10 x V1000 s/n as follows:

PR02380A12
PR02529A11
PR02529A14
PR02529A15
PR02529A17
PR02529A18
PR02529A20
PR02529A22
PR02540A13
PR02540A14

Will mention they need to be sent in clean in my reply and will ask if calib only or serv/calib

08/Feb/2024 Kate Griffiths

CALIBRATION ONLY PLEASE (they asked to be let know if anything else is needed)

08/Feb/2024 Kate Griffiths

CALIBRATION ONLY PLEASE (they asked to be let know if anything else is needed)

UPDATE. Their AWB shows wrong SRS ie.. SRS68345. I have let them know but unsure if they will change it

12/Feb/2024 Robert Connor

Received 10 x V1000 s/n PR02380A12, PR02529A11, PR02529A14, PR02529A15, PR02529A17, PR02529A18, PR02529A20, PR02529A22, PR02540A13, PR02540A14.

The units do not appear to have been cleaned since servicing last year, and 3 are missing battery doors.

Ready For quote

CGreen 15.2.24

Repair Complete Signed

CGreen 6.3.24

1480000 x 10 @ \$63.40 each

S/N, SRS, SRN

1436309 x 10

@ \$0 FOC

SRS, SRN

1440000 x 2

@ \$66.

for cleaning fee

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36253	Foetal Simulator	1410000	PR02380A12	✓
SRN36254	Foetal Simulator	1410000	PR02529A11	✓
SRN36256	Foetal Simulator	1410000	PR02529A14	✓
SRN36257	Foetal Simulator	1410000	PR02529A15	✓
SRN36258	Foetal Simulator	1410000	PR02529A17	✓
SRN36259	Foetal Simulator	1410000	PR02529A18	✓
SRN36260	Foetal Simulator	1410000	PR02529A20	✓
SRN36261	Foetal Simulator	1410000	PR02529A22	✓

1480000 x 10
@ \$63.40
~~SRS, SRN~~
S/N, SRS, SRN

UPS x 1 36x36x36cm 5.20kg

Plus add a line for Ins.

CG 15.2.24

Service Repair Sheet 68688
Contact Name
Company/ Hospital Name
Department
Position
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By

Mr Mahesha
BDI India Private Limited
Customer Support
Customer Support
919108918492
00006454
mahesha@bdi-india.com
paid
12/Feb/2024
Robert Connor

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36258	1410000	PR02529A17	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36259	1410000	PR02529A18	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36260	1410000	PR02529A20	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36261	1410000	PR02529A22	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Service Repair Sheet 68688
Contact Name
Company/ Hospital Name
Department
Position
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By

Mr Mahesha
BDI India Private Limited
Customer Support
Customer Support
919108918492
00006454
mahesha@bdi-india.com
paid
12/Feb/2024
Robert Connor

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36262	1410000	PR02540A13	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36263	1410000	PR02540A14	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Service Repair Sheet 68688

Contact Name
Company/ Hospital Name
Department
Position
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By

Mr Mahesha
BDI India Private Limited
Customer Support
Customer Support
919108918492
00006454
mahesha@bdi-india.com
paid
12/Feb/2024
Robert Connor

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36253	1410000	PR02380A12	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36254	1410000	PR02529A11	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36256	1410000	PR02529A14	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN36257	1410000	PR02529A15	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000
Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Proforma Invoice

AWB No: 9238937212 Invoice Date: 2024-02-09 Invoice No: 2402-01

SHIP FROM:
BDI I PVT. LTD.
Mahesh S
SHREESHAILA DODDAKALLA SANDRA
KANAKPURA RD.

BANGALORE, 560062
Karnataka
India
+919108918492
mahesha@bdi-india.com
Trader Type: BUSINESS
VAT No:
EORI:
TAX ID:

SHIP TO:
Viamed Ltd
Kate Griffiths
Repairs Team SR568345
15 Station Road Cross Hills
Keighley West Yorkshire
CROSS HILLS, BD20 7DT

United Kingdom
+441535634542
viamed.kate.griffiths@gmail.com
Trader Type: PRIVATE
VAT No:
EORI:

Shipper Reference: SRS6688
Receiver Reference:

Remarks:

Item	Description	Commo- dity Code	Tax Paid	Item Weight Item Total Weight	COO	Reference Type & ID	QTY	Unit Value	Sub Total Value
1	Foetal Heart Simulator	IB: 84212900		0.500 kg 5.000 kg	INDIA		10 PCS	0.05 USD	0.50 USD

Total Goods Value:
Total Invoice Amount:
Currency Code:
Terms of Payment:
Terms of Trade:
Place of Incoterm:
Reason for Export:
Type of Export:
Total Net Weight:
Total Gross Weight:
Total line items:
Number of Pallets:
Total units:
Duty / taxes acct:

0.50 USD
0.50 USD
USD

Delivered at Place

Sample
Sample
5.000kg
0.500kg
1

10.0
Receiver Will Pay

Package Marks / Other Info:

Payer of GST / VAT:

Bank Details:

INN:
OGRN:
KPP:
OKPO:
Settlement account (USD/EUR):
Settlement account (RUR):
Bank Name:
GSTIN:
GST Invoice Number:
IGST Paid:
HSN Code:
GST Invoice Date:
Against Bond:
Transport Reason:
Whether supply for exports is on payment of IGST:

29AADCB0998E1ZJ
2402-01
NA
06/02/2024
NA
NA
NA



I/We hereby certify that the information contained in the invoice is true and correct and that the contents of this shipment are as stated above.

Name:

Position:

Date of Signature: 2024-02-09

Signature:

Company Stamp

Service Repair Sheet SRS68688

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mr Mahesha

BDI India Private Limited

Customer Support

Customer Support

919108918492

00006454

mahesha@bdi-india.com

12/Feb/2024

Robert Connor

Viamed

Quote

Notes Sending in 10 x V1000 s/n as follows: PR02380A12PR02529A11PR02529A14PR02529A15PR02529A17PR02529A18PR02529A20PR02529A22PR02540A13PR02540A14Will mention they need to be sent in clean in my reply and will ask if calib only for serv/calib

05/Feb/2024 Kate Griffiths

Sending in 10 x V1000 s/n as follows:

PR02380A12

PR02529A11

PR02529A14

PR02529A15

PR02529A17

PR02529A18

PR02529A20

PR02529A22

PR02540A13

PR02540A14

Will mention they need to be sent in clean in my reply and will ask if calib only or serv/calib

08/Feb/2024 Kate Griffiths

CALIBRATION ONLY PLEASE (they asked to be let know if anything else is needed)

08/Feb/2024 Kate Griffiths

CALIBRATION ONLY PLEASE (they asked to be let know if anything else is needed)

UPDATE. Their AWB shows wrong SRS ie.. SRS68345. I have let them know but unsure if they will change it

12/Feb/2024 Robert Connor

Received 10 x V1000 s/n PR02380A12, PR02529A11, PR02529A14, PR02529A15, PR02529A17, PR02529A18, PR02529A20, PR02529A22, PR02540A13, PR02540A14.

The units do not appear to have been cleaned since servicing last year, and 3 are missing battery doors.

Ready For quote

CGreen 15.2.24

Repair Complete Signed

CGreen 6.3.24

1480000 x 10 @ \$63.40 each

S/N, SRS, SRN

1436309 x 10

@ \$0 FOC

SRS, SRN

1440000 x 2

@ \$66.

for cleaning fee

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36253	Foetal Simulator	1410000	PR02380A12	✓
SRN36254	Foetal Simulator	1410000	PR02529A11	✓
SRN36256	Foetal Simulator	1410000	PR02529A14	✓
SRN36257	Foetal Simulator	1410000	PR02529A15	✓
SRN36258	Foetal Simulator	1410000	PR02529A17	✓
SRN36259	Foetal Simulator	1410000	PR02529A18	✓
SRN36260	Foetal Simulator	1410000	PR02529A20	✓
SRN36261	Foetal Simulator	1410000	PR02529A22	✓

1480000 x 10
@ \$63.40
~~SRS, SRN~~
S/N, SRS, SRN

UPS x 1 36x36x36cm 5.20kg

Plus add a line for Ins.

CG 15.2.24