

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36314	Oxygen Analyser TEK-OX	9710203 Requires Service Manual Linking in System	 407674	0932	Oxygen Analyser TEK-OX	No	No	Complete - Repaired 28 Mar 2024 Michael Green	Case fault	00:30
SRN36314 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front is damaged. The R-17VAN Oxygen sensor is working within specification. 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front has been replaced. The R-17VAN Oxygen sensor is working within specification.										
SRN36315	Oxygen Analyser TEK-OX	9710203 Requires Service Manual Linking in System	 407675	0933	Oxygen Analyser TEK-OX	No	No	Complete - Repaired 28 Mar 2024 Michael Green	Multiple faults	02:30
SRN36315 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case is missing some screws. The main case screw retention pillars are damaged. The R-17VAN Oxygen sensor is below specification. 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The main case has been replaced. The R-17VAN Oxygen sensor is below specification and has been replaced with SN:109903.										
SRN36316	Vandagraph Tek Ox	7910201 Requires Service Manual Linking in System	 1848326	TX3600	Oxygen Analyser Tek-Ox + Quick-Ox	Yes	No	Complete - Repaired 28 Mar 2024 Michael Green	Erratic reading	01:00
SRN36316 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front is damaged. The R-17VAN Oxygen sensor is below specification. 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front has been replaced. The R-17VAN Oxygen sensor is below specification and has been replaced with SN:109904.										

Currently Viewing ITEM SRN36314 Vandagraph Tek Ox 7910201 TX3600 Oxygen Analyser Tek-Ox + Quick-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been tested. The case front has been replaced. The R-17VAN Oxygen sensor is below specification and has been replaced with SN:109904.	28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front is damaged. The R-17VAN Oxygen sensor is below specification. 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The case front has been replaced. The R-17VAN Oxygen sensor is below specification and has been replaced with SN:109904.	The Tek-Ox analyser has been tested. The case front has been replaced. The R-17VAN Oxygen sensor is below specification and has been replaced with SN:109904.

ISO REVIEW

Please Select

Instructions