



David Bell-Jones

CID28189 Opera CID28189 Type:Vandagraph Retail

David Bell-Jones 20 Meadowlands , , Ipswich, , IP10 0PP , United Kingdom

Tel 07393661084 GBP Retail Price List Vandagraph (0010)

Log Call

Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68725

SRS Created : 11 Mar 2024
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68725		Notes
SELECT * FROM viamedquoteaddress where ID='28189'		11/Mar/2024 Ryan Swaine
Company / Hospital	David Bell-Jones	11/Mar/2024 Ryan Swaine R-33DE sn.972118 recently purchased. To add back to stock and knock the price of the sensor off a new TEK-OX. Please make RS aware of this as soon as it arrives
Contact Name	David Bell-Jones	
Department		
Position		
Company Phone	07393661084	
Direct Phone	07393661084	12/Mar/2024 Ryan Swaine I have offered to take a look at his device, it may be that it can be repaired if it is just the sensor wires/connector. He will return our sensor and his O2EII analyser for evaluation. Please give it to MG 25/Mar/2024 Catherine Spence Received in Analox s/n: 50689 Sensor R-33DE S/N 483689 New R-33DE S/N 972118
Opera Account	CID28189	
Email	davidbell_jones@yahoo.co.uk	
Order Number		
Viamed ORD Number		
Date Received Into building	25 Mar 2024	
Issues?		
Items for Repair		

...	...	...	...	...	...	...	...	...	...	...
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36337	Analox O2 E11	Analox Requires Service Manual Linking in System	 50689			No	No	Unfinished		00:00
SRN36337 Customer Notes: Not working , has tried new sensor, please check unit and cables										
SRN36337 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Analox O2 E11 analyser has been tested. The sensor wire has failed. 05/Apr/2024 Michael Green The Analox O2 E11 analyser has been repaired. The sensor cable has been replaced.										
SRN36338	Oxygen Sensor Vandagraph	0110224 Requires Service Manual Linking in System	 817355	483689		No	No	No Fault Found 05 Apr 2024 Michael Green	No Fault Found	00:00
SRN36338 Customer Notes: Supplied inside unit										
SRN36338 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found. 05/Apr/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found. The sensor has been installed in the Analox analyser.										
SRN36339	Oxygen Sensor Vandagraph	0110224 Requires Service Manual Linking in System	 2356700	972118		No	No	Return Stock / Demo Stock 05 Apr 2024 Michael Green	No Fault Found	00:00
SRN36339 Customer Notes: New sensor supplied to customer , please check										
SRN36339 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found. 05/Apr/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found. The sensor is to be returned to Vandagraph.										

Currently Viewing ITEM SRN36337 Analox O2 E11 Analox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	28/Mar/2024 Michael Green The Analox O2 E11 analyser has been tested. The sensor wire has failed. 05/Apr/2024 Michael Green The Analox O2 E11 analyser has been repaired. The sensor cable has been replaced.	Non added Yet

ISO REVIEW

Please Select

Instructions