

JG Full, SH Full



Scuba Elite

 CID28264 Opera CID28264 Type:Vandagraph Trade

Scuba Elite 39 Kaya Gob. N. Debrot, , Kralendijk, , Bonaire

Tel 00599 700 2171 GBP Trade Price List Vandagraph (0009)

Proforma Credit Limit 0.00GBP

Add Issue

 Account Home

 Main Details

Account Memos

 Sales History

Stock References

⌚ Cust./Supp. Returns

 Service
Visits

 Distributor Agreements

Documents
Files

 **Linked
Issues**

Regulatory Agreements

SRS68733

SRS Created : 14 Mar 2024

Created By Robert Connor

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

ADD DOCUMENT TO SRS :	Document Description
-----------------------------	-------------------------

Choose a file to upload: No file chosen

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Uploaded Documents

14 Mar 2024 SRS68733 SRN36312 Michael Lamb

Service Repair Sheet 68733 SELECT * FROM viamedquoteaddress where ID='28264'		Notes 14/Mar/2024 Robert Connor 14/Mar/2024 Robert Connor Received 2 x tek-ox s/n TX3449, TX3451, with blue t-adapters. Items returned for unknown reason, serial number search shows they were sold to this customer. 14/Mar/2024 Michael Lamb relinked to correct customer and Updated details 27/Mar/2024 Catherine Spence No paperwork in ducket, in engineers room, in incorrect labelled ducket 04/Apr/2024 Ryan Swaine I have quote for new sensors at trade pricing LINKED ISSUE NOTES: 325722: AutoGenerated Issue SRS68733 Appears to be Complete
Company / Hospital	Scuba Elite	
Contact Name	Pascal van Empelen	
Department		
Position		
Company Phone	599 700 2171	
Direct Phone	599 700 2171	
Opera Account	CID28264	
Email	pascal@scuba-elite.com	
Order Number		
Viamed ORD Number		
Date Received Into building	14 Mar 2024	

Issues?

325722

Items for Repair

... ..

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36312	Oxygen Analyser TEK-OX	7910210 Requires Service Manual Linking in System	 1663325	TX3449	Oxygen Analyser Tek-Ox	Yes	No	Complete - Repaired 05 Apr 2024 Michael Green	Multiple faults	00:45
SRN36312 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The unit is working as expected. The case screws are rusty. The R-17VAN Oxygen sensor is below specification. 05/Apr/2024 Michael Green The Tek-Ox analyser has been repaired. The R-17VAN Oxygen sensor has been replaced with SN:109923. Some case screws have been replaced. New batteries have been fitted.										
SRN36313	Oxygen Analyser TEK-OX	7910210 Requires Service Manual Linking in System	 1663327	TX3451	Oxygen Analyser Tek-Ox	Yes	No	Complete - Repaired 05 Apr 2024 Michael Green	Multiple faults	00:45
SRN36313 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The unit is working as expected. The case screws are rusty. The R-17VAN Oxygen sensor is below specification. 05/Apr/2024 Michael Green The Tek-Ox analyser has been repaired. The R-17VAN Oxygen sensor has been replaced with SN:109924. Some case screws have been replaced. New batteries have been fitted.										

Currently Viewing ITEM SRN36312 Oxygen Analyser TEK-OX 7910210 TX3451 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The R-17VAN Oxygen sensor has been replaced with SN:109924. Some case screws have been replaced. New batteries have been fitted.	28/Mar/2024 Michael Green The Tek-Ox analyser has been tested. The unit is working as expected. The case screws are rusty. The R-17VAN Oxygen sensor is below specification. 05/Apr/2024 Michael Green The Tek-Ox analyser has been repaired. The R-17VAN Oxygen sensor has been replaced with SN:109924. Some case screws have been replaced. New batteries have been fitted.	The Tek-Ox analyser has been repaired. The R-17VAN Oxygen sensor has been replaced with SN:109924. Some case screws have been replaced. New batteries have been fitted.

ISO REVIEW

Please SelectInstructions