

Service Repair Sheet 68617

Contact Name	Vincent Wong
Company/ Hospital Name	SP Global PLT
Direct Phone	60193200123
General Phone	60193200123
Opera Account	00006263
Email	spglobal2011@gmail.com
Order Number	Proforma paid
Date Received	27/Mar/2024
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN36341	1410000	PR01883A19	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
