

Service Repair Sheet 68716

| | |
|------------------------|--|
| Contact Name | Matthew Jameson |
| Company/ Hospital Name | Sunderland Royal Hospital |
| Department | Clinical Engineering |
| Position | Senior Clinical Engineering Technician |
| Direct Phone | 01915699933 |
| Opera Account | 00004992 |
| Email | matthew.jameson@nhs.net |
| Order Number | RLNP400097956 |
| Date Received | 06/Mar/2024 |
| Booked in By | Robert Connor |

| | | | | |
|----------|---------|--------|----------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN36291 | 0310030 | 040019 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 040019 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

| | | | | |
|----------|---------|--------|----------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN36292 | 0310030 | 040026 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 040026 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

| | | | | |
|----------|---------|---------|----------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN36293 | 0310030 | 0401379 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |

Parts Replaced

Qty: 1 0380000
Qty: 1 0330203
Qty: 1 0330212

Tom Thumb TT480 0401378 has been stripped and cleaned then reassembled with new O rings and a new gauge. The two valves have been checked and reset before QA.

| | | | | |
|----------|---------|---------|----------------|--|
| Repair | Ref | S/N | Equipment Type | |
| SRN36294 | 0310030 | VMA0080 | Tom Thumb | Complete - Repaired Time :0 Hour(s) |

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA0080 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.