

Service Repair Sheet 68645

Contact Name Morne Leukes

Company/ Hospital Name SSEM Mthembu Medical (Pty) Ltd

General Phone 000114307000 Opera Account CID11237

Email mornel@ssemmthembu.co.za

Order Number Quote paid
Date Received 21/Mar/2024
Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN36326 1410000 PR02810A11 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type SRN36327 1410000 PR02810A12 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1430309 Qty: 1 1480000

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type
SRN36328 1410000 PR02810A13 Foetal Simulator Comp.

SRN36328 1410000 PR02810A13 Foetal Simulator Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair Ref S/N Equipment Type
SRN36329 1410000 PR02810A14 Foetal Simulator Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.