

Service Repair Sheet SRS68689

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Damion Walters

Huntleigh Healthcare Ltd

02920 485885

02920485885

00011875

damion.walters@arjo.com

16/May/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC
Date: 16/5/24

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 06/Feb/2024 Steve Hardaker

06/Feb/2024 Steve Hardaker

Returning a V1000 they are having problems with, not as high amplitude as previously and it responds differently at different angles. Needs a service with the transducer cushion replacing.

s/n PR02467A11.

16/May/2024 Robert Connor

Received 1 x V1000 s/n PR02467A11, with grey silicone cover and blue fabric carry case.

Ready For quote

CCNEEN 16.5.24

Repair Complete Signed

CCNEEN 23.5.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36450	Foetal Simulator	1410000	PR02467A11	N

1480000 x 1 @ £60
S/N, SRS, SRN

1430309 x 1 FOC
SRS, SRN

UPS x 1 £12.