

23/05/2024, 13:20

SRS View

SRN36463	MixChek	mixchek Requires Service Manual Linking in System	 22616	243306	Mixchek	No	No	Complete - Repaired 23 May 2024 Michael Green	Display fault	02:00
SRN36463 Engineer Notes: INTERNAL NOTES not for customer discussion 23/May/2024 Michael Green The Mixchek analyser has been tested. Both displays have segment faults. The R-33S1 Oxygen sensor dates from 2019 and has expired. 23/May/2024 Michael Green The Mixchek analyser has been repaired. The displays have been replaced. The R-33S1 Oxygen sensor has been replaced with SN:121918. The gas sample tubing has been replaced.										

Currently Viewing ITEM SRN36463 MixChek mixchek 243306 Mixchek

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Mixchek analyser has been repaired. The displays have been replaced. The R-33S1 Oxygen sensor has been replaced with SN:121918. The gas sample tubing has been replaced.	23/May/2024 Michael Green The Mixchek analyser has been tested. Both displays have segment faults. The R-33S1 Oxygen sensor dates from 2019 and has expired. 23/May/2024 Michael Green The Mixchek analyser has been repaired. The displays have been replaced. The R-33S1 Oxygen sensor has been replaced with SN:121918. The gas sample tubing has been replaced.	The Mixchek analyser has been repaired. The displays have been replaced. The R-33S1 Oxygen sensor has been replaced with SN:121918. The gas sample tubing has been replaced.

ISO REVIEW

Please Select

Instructions