

COMPANY OPERATING PROCEDURES

Maxtec Max-250 (PN 0110428), Max-250E (PN 0110429) Max-22ESF (PN 0110430)
O₂ Sensor Test Procedure

VM3/COP/37.27

Test & Equipment Required

Visual check only - no test equipment required.

Method.

1. Attach Serial number stickers to carton