



Dive-In Larnaca

Five-In Larnaca Lordos Seagate Block A, Tasos Mitsopoulos Avenue, (Formerly Piale Pasa), Larnaca, , 6027, United Kingdom

Tel +357 24627469 GBP Trade Price List Vandagraph (0009)

 Log Cal

Add Issue

Proforma Credit Limit 0.00GBP

VAT CY10096116G

Account
Home

 Main Details

Account Memos

 Sales History

Stock References

 Cust./Supp. Returns

 Service
Visits

Distributor Agreements

Documents
Files

Linked Issues

Regulatory Agreements

SRS68801

SRS Created : 28 May 2024

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS :	Document Description
-----------------------------	-------------------------

Choose a file to upload: No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Linked to Order Reference 🔍 **150640**

Service Repair Sheet 68801		Notes 28/May/2024 Ryan Swaine 28/May/2024 Ryan Swaine TEK-OX TX 4258 Will not turn on 04/Jun/2024 Robert Connor Received 1 x tek-ox s/n TX4258, with yellow carry case, blue tee, flow diverter and R-17VAN s/n 108624. 08/Jun/2024 Catherine Spence Engineers room LINKED ISSUE NOTES: 332885: AutoGenerated Issue SRS68801 Appears to be Complete
Company / Hospital	Dive-In Larnaca	
Contact Name	Hannah Baker	
Department		
Position	Director	
Company Phone	+357 24627469	
Direct Phone	00357 96795731	
Opera Account	DIVEIN	
Email	office@dive-in.com.cy	
Order Number		
Viamed ORD Number		
Date Received Into building	04 Jun 2024	
Type	Warranty	
Issues?	332885	

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36485	Vandagraph Tek Ox	7910201 Requires Service Manual Linking in System	 2248306	TX4258	Tek-Ox Auto + Quick-Ox	Yes	No	Complete - Repaired 19 Jun 2024 Michael Green	Not Switching On	00:00
SRN36485 Engineer Notes: INTERNAL NOTES not for customer discussion 19/Jun/2024 Michael Green The Tek-Ox analyser has been tested. The battery door battery contact is not making a good connection. 19/Jun/2024 Michael Green The Tek-Ox analyser has been repaired under warranty. The battery door contact has been replaced. New batteries have been fitted.										
SRN36486	Oxygen Sensor Vandagraph	0110217 Requires Service Manual Linking in System	 2286148	108624	Oxygen sensor R-17VAN	Yes	No	No Fault Found 19 Jun 2024 Michael Green	No Fault Found	00:00
SRN36486 Engineer Notes: INTERNAL NOTES not for customer discussion 19/Jun/2024 Michael Green The R-17VAN Oxygen sensor has been tested. No fault was found.										

Currently Viewing ITEM SRN36485 Oxygen Sensor Vandagraph 0110217 108624 Oxygen sensor R-17VAN

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The R-17VAN Oxygen sensor has been tested. No fault was found.	19/Jun/2024 Michael Green The R-17VAN Oxygen sensor has been tested. No fault was found.	The R-17VAN Oxygen sensor has been tested. No fault was found.

ISO REVIEW

Please Select Instructions