


## ATA Oxygen sensor Pt No 9212-94



Electrical connections. 10.5mV in Air  
Red is =+ve Black is -ve

Mechanical adapter pt no;-

Use R-22 style needs electrical adapter 3 pin – 2 pin.

