

Viamed Limited - 15 Station Road - Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68858 Contact Name Company/ Hospital Name Direct Phone General Phone

Opera Account Email Order Number Date Received Booked in By

Mark Brucks Tenacore LLC 800297-2241 8002972241 00007996 mark.brucks@tenacore.com paid proforma 31/Jul/2024 Robert Connor

Repair

S/N SRN36572 1410000 PR02976A11 Foetal Simulator

Equipment Type

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.