

DL Full, HL Full, AM Full, SL Half





Sergio Reyes Saez

CID29705 Opera CID29705 Type:Vandagraph Retail

Sergio Reyes Saez Avenida del Sur 1B, , Torrevieja , Alicante, 03183, Spain

Tel 0034 644302103 GBP Retail Price List Vandagraph (0010)

Log Call

Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68848

SRS Created : 16 Jul 2024
Created By Ryan Swaine
Add Watch

- [Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68848		Notes 16/Jul/2024 Ryan Swaine 16/Jul/2024 Ryan Swaine VN202 mk1 sn. 2262 Needs new power switch, as it is loose, Internal Calibration, currently showing 0.6 and new sensor. Estimate of costs quoted: The cost for the new power button and calibration = GBP £25 R-17VAN O2 sensor = GBP £50 Postage = GBP £14 Total = £89.00 06/Aug/2024 Robert Connor Received 1 x VN202 s/n 2262 08/Aug/2024 Catherine Spence engineers room 27/Aug/2024 Catherine Spence Engineers Room
Company / Hospital	Sergio Reyes Saez	
Contact Name	Sergioo Reyes Saez	
Department		
Position		
Company Phone	0034 644302103	
Direct Phone	0034 644302103	
Opera Account	CID29705	
Email	buceoburbujas@gmail.com	
Order Number		
Viamed ORD Number		
Date Received Into building	06 Aug 2024	
Type	Quote Before Repair Move to Repair	
Issues?		
Items for Repair		
...		

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37037	Oxygen Analyser VN202	7910110 Requires Service Manual Linking in System	 1518550	02262	VN202mkII - Manual Switch Off	No	No	Unfinished		00:00
SRN37037 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Aug/2024 Michael Green The VN202 analyser has been tested. The power button and battery lead need to be replaced.										

Currently Viewing ITEM SRN37037 Oxygen Analyser VN202 7910110 02262 VN202mkII - Manual Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	28/Aug/2024 Michael Green The VN202 analyser has been tested. The power button and battery lead need to be replaced.	Non added Yet

ISO REVIEW

Please Select

Instructions