

vmserver10.thevault.me.uk/intranet/databases/repairs/viewrepair2.php?zz=1&vui=6&u

Service Repair Sheet 6886Z

Company / Hospital	Royal London Hospital
Contact Name	Richard Aldridge
Department	Adult Critical Care Unit
Position	Lead Technologist
Company Phone	02073777000
Direct Phone	020 7480 4622
Opera Account	00003030
Email	richard.aldrige1@nhs.net
Order Number	41048352
Vamed ORD Number	
Date Received Into building	31 Jul 2024
Type	Repair Approved
Issues?	338143

Notes

30/Jul/2024 Steve Hardaker
30/Jul/2024 Steve Hardaker
Returning a MaxBlend for service, he isn't sure if it is version 1 or 2 but
31/Jul/2024 Robert Connor
Received 1 x maxblend s/n BDF05737
08/Aug/2024 Catherine Spence
On quote with customer
14/Aug/2024 Kate Griffiths
PO 41048352 attached
21/Aug/2024 Philip Crossley
In addition the monitor part of the blender needs 0339950 MaxBlend Front
fine until I pressed some of the buttons during testing.
27/Aug/2024 Catherine Spence
On quote with customer
28/Aug/2024 Steve Hardaker
Followed up with Richard Aldridge. As we already have a PO for the service.
28/Aug/2024 Steve Hardaker
They have asked for a second quote for the additional parts and a second ord

LINKED ISSUE NOTES

338143

Added by Kate Griffiths sent to Catherine Spence

Service Repair Sheet:6886Z has been Approved with Customer Order number: -

19 Aug 2024 Catherine Spence
was given back to engineer last week

19 Aug 2024 Kate Griffiths
Done

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description
SRN36571	Blender	Requires Service Manual Linking in System		BDF05737	MaxBlend

SRN36571 Engineer Notes: INTERNAL NOTES not for customer discussion

01/Aug/2024 Philip Crossley

Routine service and calibration test. Maxblend I and II share the same service kit.

20/Aug/2024 Philip Crossley

There are 2 bolts missing from one of the balance blocks. Fortunately I have a scrap Bird blender I can take the bolts from as I struggle sizing the

21/Aug/2024 Philip Crossley

In addition the monitor part of the blender needs 0339950 MaxBlend Front Cover and 0320500 MaxBlend Sensor Cable. The monitor is just falling

Currently Viewing

Items Requested for Repair

Item	Qty	By	Date Requested	Status
0380061	1	Philip Crossley	01/Aug/2024	request
R200452	1	Philip Crossley	01/Aug/2024	completed
0339950	1	Philip Crossley	21/Aug/2024	Quote
0320500	1	Philip Crossley	21/Aug/2024	Quote

Item notes

Non Supplied