

CS Full, KG Full, SH 02:30:00 PM For 3 Hours, ML Full



Sergio Reyes Saez

CID29705 Opera CID29705 Type:Vandagraph Retail

Sergio Reyes Saez Avenida del Sur 1B, , Torrevieja , Alicante, 03183, Spain

Tel **0034 644302103** GBP Retail Price List Vandagraph (0010)

Log CallAdd Issue

Proforma Credit Limit 0.00GBP

- Account HomeMain DetailsAccount MemosSales HistoryStock ReferencesCust./Supp. ReturnsService VisitsDistributor AgreementsDocuments Files
- Linked IssuesRegulatory Agreements

SRS68848

SRS Created : 16 Jul 2024
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose fileNo file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Linked to Order Reference 151900

[View 17:28:51 28 Aug 2024](#) (SRS68848.pdf) ✖

Service Repair Sheet 68848		Notes
Company / Hospital	Sergio Reyes Saez	16/Jul/2024 Ryan Swaine
Contact Name	Sergioo Reyes Saez	16/Jul/2024 Ryan Swaine
Department		VN202 mk1 sn. 2262
Position		Needs new power switch, as it is loose, Internal Calibration, currently showing 0.6 and new sensor.
Company Phone	0034 644302103	Estimate of costs quoted:
Direct Phone	0034 644302103	The cost for the new power button and calibration = GBP £25
Opera Account	CID29705	R-17VAN O2 sensor = GBP £50
Email	buceoburbujas@gmail.com	Postage = GBP £14
Order Number		Total = £89.00
Viamed ORD Number		06/Aug/2024 Robert Connor
Date Received Into building	06 Aug 2024	Received 1 x VN202 s/n 2262
Type	Quote Before Repair Move to Repair	08/Aug/2024 Catherine Spence engineers room
Issues?	339928	27/Aug/2024 Catherine Spence Engineers Room
		LINKED ISSUE NOTES: 339928 : AutoGenerated Issue SRS68848 Appears to be Complete
		06 Sep 2024 Catherine Spence noted
Items for Repair		

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)	
SRN37037	Oxygen Analyser VN202	7910110 Requires Service Manual Linking in System	 1518550	02262	VN202mkII - Manual Switch Off	No	No	Complete - Repaired 03 Sep 2024 Michael Green	On/off button fault	01:30	   RAN1851900-1
SRN37037 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Aug/2024 Michael Green The VN202 analyser has been tested. The power button and battery lead need to be replaced. 03/Sep/2024 Michael Green The VN202 analyser has been repaired. The power button and battery lead have been replaced.											

Currently Viewing ITEM SRN37037 Oxygen Analyser VN202 7910110 02262 VN202mkII - Manual Switch Off

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The VN202 analyser has been repaired. The power button and battery lead have been replaced.	28/Aug/2024 Michael Green The VN202 analyser has been tested. The power button and battery lead need to be replaced. 03/Sep/2024 Michael Green The VN202 analyser has been repaired. The power button and battery lead have been replaced.	The VN202 analyser has been repaired. The power button and battery lead have been replaced.

▲

ISO REVIEW

Please Select

Instructions