9/30/24, 10:34 AM SRS View



## **SRS68906**

SRS Created : 20 Sep 2024 Created By Steve Hardaker Add Watch

Handle with care

Add Items to Supplier Returns Box

Print Barcodes
Print A4 Sheet
Split Items into Different SRS Numbers
Edit Details

### **Upload Document to SRS**

ADD
DOCUMENT
TO SRS:
Document
Description

Next

Add

Return for Credit / Return to Stock
Unopened - will apply to all items on srs
Clear From System - Force from System. will apply to all items on srs
Add notes to SRS

#### **Uploaded Documents**

25 Sep 2024 SRS68906 SRN37102 Decontamination Certificate Robert Connor

Service	Repair Sheet 68906	Notes					
Company / Hospital	Sunderland Royal Hospital	20/Sep/2024 Steve Hardaker					
Contact Name	Matthew Jameson	20/Sep/2024 Steve Hardaker  Sending 11 Tom Thumbs for service, serial numbers below:					
Department	Clinical Engineering	VMC9071, 40022, ,VMA0083, 40092, VMA0109, VMA0087, VMA0081,					
Position	Senior Clinical Engineering Technician	VMA0077, VMA0114, VMA0104, VMA106 (this one has been dropped and is missing pressure gauge window).					
Company Phone	01915656256	Quote including the repair. 25/Sep/2024 Robert Connor					
Direct Phone	01915699933	Received 11 x tom thumb s/n 040022, 040092, VMA0077, VMA0081,					
Opera Account	00004992	VMA0083, VMA0087, VMA106, VMA0104, VMA0109, VMA0114, VMC9071.					
Email	matthew.jameson@nhs.net	VIVICED / 1.					

Order Number	
Viamed ORD Number	
Date Received Into building	25 Sep 2024
Туре	Quote Before Repair Move to Repair
Issues?	

		Quote Before Repair Move to Repair									
Issues?											
Items for	Repai	r 			11						
SRN	Equipn	nent	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37102	Tom Thumb		0310030 Requires Service Manual Linking in System	429990	040022	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37102 26/Sep/202 Routine se	4 Philip			AL NOTES no	ot for customer	discussion					**
SRN37103	Tom		0310030 Requires Service Manual Linking in System	429992	040092	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37103 26/Sep/202 Routine se	4 Philip			AL NOTES no	ot for customer	discussion		11			11
SRN37104	Tom Thumb	)	0310030 Requires Service Manual Linking in System	429962	VMA0077	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37104 26/Sep/202 Routine se	4 Philip		otes: INTERN	AL NOTES no	ot for customer	discussion		11			<u>II</u>
SRN37105	Tom	)	0310030 Requires Service Manual Linking in System	429965	VMA0081	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37105 26/Sep/202 Routine se	4 Philip			AL NOTES no	ot for customer	discussion					
SRN37106	Tom Thumb	)	0310030 Requires Service Manual Linking in System	429975	VMA0083	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37106 26/Sep/202 Routine se	4 Philip			AL NOTES no	ot for customer	discussion				_	
SRN37107	Tom Thumb		0310030 Requires Service Manual	429958	VMA0087	Tom Thumb TT480		No	Quote 26 Sep 2024	New	00:00

9/30/24. 10:34 AM SRS View

/24, 10:34 AM	1				SRS Vie	V				
		Linking in System						Philip Crossley		
SRN37107 26/Sep/202 Routine ser	4 Philip Cr	lotes: INTERNA ossley	AL NOTES no	t for custome	r discussion					
SRN37108	Tom Thumb	0310030 Requires Service Manual Linking in System	2411382	VMA106	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
26/Sep/202	4 Philip Cr	lotes: INTERNA ossley so it doesn`t n				face.				
SRN37109	Tom Thumb	0310030 Requires Service Manual Linking in System	429966	VMA104	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37109 26/Sep/202 Routine ser	4 Philip Cr	lotes: INTERNA ossley	AL NOTES no	t for custome	r discussion					
SRN37110	Tom Thumb	0310030 Requires Service Manual Linking in System	429977	VMA109	Tom Thumb	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37110 26/Sep/202 Routine ser	4 Philip Cr	lotes: INTERNA ossley	AL NOTES no	t for custome	r discussion					-1,
SRN37111	Tom Thumb	0310030 Requires Service Manual Linking in System	429960	VMA114	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37111 26/Sep/202 Routine ser	4 Philip Cr	lotes: INTERNA ossley	AL NOTES no	for customer	discussion					
SRN37112	Tom Thumb	0310030 Requires Service Manual Linking in System	429982	VMC9071	Tom Thumb TT480	No	No	Quote 26 Sep 2024 Philip Crossley	New	00:00
SRN37112 26/Sep/202 Routine ser	4 Philip Cr	lotes: INTERNA	AL NOTES no	t for custome	r discussion				'	-11

# Currently Viewing ITEM SRN37102 Tom Thumb 0310030 VMC9071 Tom Thumb TT480

Create a Meeting Issue

Items Requested for Repair						Engineer Notes	Notes To Customer
Item	Qty	IRV I	Date Requested	Status	Non Supplied	26/Sep/2024 Philip Crossley Routine service.	Non added Yet
0380000		Philip Crossley	26/Sep/2024	Quote		Roduine service.	

9/30/24, 10:34 AM SRS View

#### ISO REVIEW

Standard customer - service

Instructions

Standard customer - service

Standard customer - service No requirement to escalate to a complaint or

non conformance.