

Viamed Limited - 15 Station Road - Cross Hills Keighley - West Yorkshire - BD20 7DT - United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68862

Contact Name Company/ Hospital Name Department

Position Direct Phone General Phone

Opera Account

Email Order Number

Date Received Booked in By

Richard Aldridge Royal London Hospital Adult Critical Care Unit Lead Technologist 020 7480 4622

02073777000 00003030

richard.aldridge1@nhs.net

41061588 31/Jul/2024 Robert Connor

Repair

Ref S/N SRN36571 0310265 BDF05737 Equipment Type Blender

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 0380061 Qty: 1 R200P02 Qty: 1 0339950 Qty: 1 0131625

Blender BDF05737 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.

The sensor cable and front cover for the electronics have been replaced.