


Universal Mounting Clamp Instructions
Part Number: 0121200



The Universal Mounting is used to attach instruments to IV poles, shelves and other objects up to 3.8cm thick. The Mounting Clamp offers 360-degree rotation and 180-degree movement in all directions providing maximum flexibility in selecting a mounting site.


The clamp is supplied in two parts, the Clamp Body Assembly and Swivel Mount Assembly. To attach the Universal Clamp to the Swivel Mount use the Mounting Screw and Thumb Wheel shown in the diagram above.

Slots in the base of the Swivel Mount allow 360-degree rotation in 45-degree increments. When the desired orientation is obtained, insert the index screw into the slot and tighten the thumb wheel.

To attach the instrument to the ball mount loosen the Adjustment Knob until the ball mount screw is loose. Insert the Instrument Mounting Screw into the mount of the instrument and tighten using the Ball Thumb Wheel.

Mount the Universal Clamp in the desired location and tighten the Clamping Screw. Adjust instrument to desired position and tighten the Adjustment knob to secure the instrument in place.

Universal Mounting Clamp Instructions
Part Number: 0121200



The Universal Mounting is used to attach instruments to IV poles, shelves and other objects up to 3.8cm thick. The Mounting Clamp offers 360-degree rotation and 180-degree movement in all directions providing maximum flexibility in selecting a mounting site.


The clamp is supplied in two parts, the Clamp Body Assembly and Swivel Mount Assembly. To attach the Universal Clamp to the Swivel Mount use the Mounting Screw and Thumb Wheel shown in the diagram above.

Slots in the base of the Swivel Mount allow 360-degree rotation in 45-degree increments. When the desired orientation is obtained, insert the index screw into the slot and tighten the thumb wheel.

To attach the instrument to the ball mount loosen the Adjustment Knob until the ball mount screw is loose. Insert the Instrument Mounting Screw into the mount of the instrument and tighten using the Ball Thumb Wheel.

Mount the Universal Clamp in the desired location and tighten the Clamping Screw. Adjust instrument to desired position and tighten the Adjustment knob to secure the instrument in place.

Universal Mounting Clamp Instructions
Part Number: 0121200



The Universal Mounting is used to attach instruments to IV poles, shelves and other objects up to 3.8cm thick. The Mounting Clamp offers 360-degree rotation and 180-degree movement in all directions providing maximum flexibility in selecting a mounting site.

The clamp is supplied in two parts, the Clamp Body Assembly and Swivel Mount Assembly. To attach the Universal Clamp to the Swivel Mount use the Mounting Screw and Thumb Wheel shown in the diagram above.

Slots in the base of the Swivel Mount allow 360-degree rotation in 45-degree increments. When the desired orientation is obtained, insert the index screw into the slot and tighten the thumb wheel.

To attach the instrument to the ball mount loosen the Adjustment Knob until the ball mount screw is loose. Insert the Instrument Mounting Screw into the mount of the instrument and tighten using the Ball Thumb Wheel.

Mount the Universal Clamp in the desired location and tighten the Clamping Screw. Adjust instrument to desired position and tighten the Adjustment knob to secure the instrument in place.