

Viamed Limited · 15 Station Road · Cross Hills Keightey · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68920

Contact Name

Company/ Hospital Name

Direct Phone General Phone

Opera Account

Email

Order Number Date Received Booked in By

Hugo da Silva

Royal Stoke University Hospital

01782 556936 01782715444 00012132

hugo.silva@uhnm.nhs.uk

X027097 07/Oct/2024 Robert Connor

Repair SRN37123 1410000 PR0466A13

S/N

Equipment Type Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

1480000 Qty: 1 1430309 Qty: 1

V1000 has had transducer interface cushion replaced and calibration has been checked.