



## Service Repair Sheet SRS68938

Contact Name  
 Company/ Hospital Name  
 Department  
 Position  
 Direct Phone  
 General Phone  
 Opera Account  
 Email  
 Order Number  
 Date Received  
 Booked in By  
 Main Company  
 Type Return

Filipe  
 Gama Aviation Plc  
  
 01252553029  
 01252 553029  
 CID19740  
 medical@gamaaviation.com  
  
 28/Oct/2024  
 Robert Connor  
 Viamed  
 Quote

## VIAMEDclean

## Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☒

Signed: RF  
Date: 28/10/24

## Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 24/Oct/2024 Aqib Majeed

24/Oct/2024 Aqib Majeed

Customer is returning a Maxblend 2 Low flow Air/oxygen Blender SN FA56833001 for annual performance check

24/Oct/2024 Aqib Majeed

Also requires a new charger on the quote as one in the device is broken

28/Oct/2024 Robert Connor

Received 1 x MaxBlend2 s/n FA56833001, with MAX550E s/n HH82199025, blender flow diverter, blender nip, and pole/rail mounting clamp. Front bezel of blender is cracked, and mounting plate on clamp is loose due to missing screw.

Ready For quote

C Green 30.10.24

Repair Complete Signed \_\_\_\_\_

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37141	Blender	0310291	FA56833001	N
SRN37142	Oxygen Sensor	0110452	HH82199025	Yes

0380060 x 1 @ £90  
S/N, SRS, SRN

0121318 x 1 @ £52.50  
SRS, SRN

0339950 x 1 @ £60  
SRS, SRN

UPS x 1 @ £12.