

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

> Complete - Repaired Time: 0 Hour(s)

Service Repair Sheet 68932

Contact Name

Company/ Hospital Name

Department Direct Phone

General Phone

Opera Account

Email Order Number

Date Received Booked in By

Vincent Ochieng

University College Hospital Medical Physics Department

02034474984

Robert Connor

0845 1555000/02034 567890

00003420

v.ochieng@nhs.net RRVN400333914 22/Oct/2024

Repair Ref S/N Equipment Type SRN37138 1410000 PR01898A10 Foetal Simulator

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

The V1000 wouldn't turn on.

I found the unit had been opened and the battery lead was reversed.

The V1000 has also had the transducer interface cushion replaced and calibration has been checked.