

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68966

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone General Phone

Opera Account

Email

Order Number Date Received Booked in By

Hussein Remtulla

St James University Hospital

Clinical Engineering

Medical Electronics Technician

01132066882 01132433144 00002570

hussein.remtulla@nhs.net

RR8N400537344 28/Nov/2024 Robert Connor

Repair

Ref

S/N SRN37472 0111230 333728

Equipment Type

Oxygen Analyser

Unable to Repair Time: 0 Hour(s)

The AX300 Oxygen analyser has been tested. The LCD has been damaged. No replacement PCB is available. We cannot repair the unit.

Repair

Ref

S/N

Equipment Type SRN37473 0111230 240656

Oxygen Analyser

Complete - Repaired

Time: 0.5 Hour(s)

Parts Replaced

Qty: 1 Qty: 1 0131215 0121216

Qty: 0.5 0140004

The AX300 Oxygen analyser has been repaired. A new case and input connector have been fitted.

Repair

SRN37474

Ref

S/N 0111230 261265

Equipment Type

Oxygen Analyser

Unable to Repair Time: 0 Hour(s)

The AX300 Oxygen analyser has been tested. The PCB will not power up. No replacement PCB is available. We cannot repair the unit.