

Service Repair Sheet 69012

Contact Name
Company/ Hospital Name
Direct Phone
Opera Account
Email
Order Number
Date Received
Booked in By

Richard Wood
University Hospital Monklands
01698752074
00000070
Richard.Woods@lanarkshire.scot.nhs.uk
LMP15029679
29/Jan/2025
Robert Connor

Repair	Ref	S/N	Equipment Type	Complete - Repaired
SRN37593	1410000	PR02894A14	Foetal Simulator	Time :0 Hour(s)

Parts Replaced

Qty: 1	1430309
Qty: 1	1480000

V1000 has had transducer interface cushion replaced and calibration has been checked.
