Service Repair Sheet 69044

Contact Name Mark Phipps

Company/ Hospital Name Smit Mobile Equipment
Department Mobile Medical Field Service

Position Service Manager
Direct Phone 0127664490
General Phone 0127664490
Opera Account 00020025

Email mark.phipps@smit.eu

Order Number MP10606
Date Received 25/Feb/2025
Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37646 0111235 247391 Oxygen Monitor Complete - Repaired Time :0.5 Hour(s)

Parts Replaced

Qty: 0.5 0140005 Qty: 1 0131215

The MX300 Oxygen monitor monitor has been serviced and the sensor input connector has been replaced.

Repair Ref S/N Equipment Type SRN37647 0111235 287917 Oxygen Monitor Complete - Repaired

Time :0.5 Hour(s)

Parts Replaced

Qty: 0.5 0140005 Qty: 1 0121217

The MX300 Oxygen monitor monitor has been repaired. The case and sensor input connector have been replaced.

Repair Ref S/N Equipment Type

SRN37648 0111235 331755 Oxygen Monitor Complete - Repaired Time :0.25 Hour(s)

Parts Replaced

Qty: 1 0121208 Qty: 0.25 0140005

The MX300 Oxygen monitor monitor has been repaired. The keypad has been replaced.

Repair Ref S/N Equipment Type

SRN37649 0131202 0000003 Misc. Cable End Of Life
Time :0 Hour(s)

Parts Replaced

Qty: 1 0131202

The Oxygen sensor cable was found to be open circuit and has been replaced with SN:001119.

Service Repair Sheet 69044

Contact Name Mark Phipps

Company/ Hospital Name Smit Mobile Equipment
Department Mobile Medical Field Service

Position Service Manager
Direct Phone 0127664490
General Phone 0127664490
Opera Account 00020025

Email mark.phipps@smit.eu

Order Number MP10606
Date Received 25/Feb/2025
Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37650 0131202 0004767 Misc. Cable No Fault Found

Time: 0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair Ref S/N Equipment Type

SRN37651 0131202 0010575 Misc. Cable No Fault Found

Time: 0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.