

Ref: SRS69115

To attn. Kate Griffiths
Viamed Ltd.

Prague, May 5th., 2025

Dear Kate,

after our E-mailing, we are sending you to back **1x R-22A sensor, s/n 169712 F4**.
The sensor doesn't work, it isn't possible to calibrate it. After installation, the value is 0,9mV only. I would like to ask you for replacement under warranty, if it is possible.

Thanks so much,
best regards


Oskar Silechta
Chromservis Czech