

Linked to Order Reference 156445

-  [View 17:14:20 24 Apr 2025](#) (Repair Sheet SRS69099 20250424.pdf) ✖
-  [View 17:14:47 24 Apr 2025](#) (Requested Quote SRS69099 20250424.pdf) ✖
-  [View 17:15:01 24 Apr 2025](#) (Customer Letter SRS69099 20250424.pdf) ✖
-  [View 12:50:56 25 Apr 2025](#) (VPO-RFL626714.pdf) ✖

Service Repair Sheet 69099		Notes
Company / Hospital	North Middlesex University Hospital	10/Apr/2025 Steve Hardaker
Contact Name	Kamal Pacitti	10/Apr/2025 Steve Hardaker
Department	Clinical Engineering Department	Sending 3 more blenders back for overhaul service, s/nos to be advised.
Position	Specialist Clinical Engineer	24/Apr/2025 Robert Connor
Company Phone	02088872000	Received 3 x blender s/n BX1854196, BX1854639, BX1855845 24/Apr/2025 Catherine Spence
Direct Phone	02088873790	Quote added, in checking
Opera Account	00003070	25/Apr/2025 Aqib Majeed
Email	kamal.pacitti@nhs.net	Po received and attached 28/Apr/2025 Catherine Spence with engineer
Order Number	RFL626714	30/Apr/2025 Philip Crossley
Viamed ORD Number		The chrome on the O2 inlet of BX1855845 has just started flaking off in my hands. SH is contacting Inspiration for price etc, then I need to Quote the customer for the additional part. 02/May/2025 Catherine Spence
Date Received Into building	24 Apr 2025	With Phill and Steve H.
Type	Repair Approved	08/May/2025 Steve Hardaker
Issues?	362598	Have asked Inspiration Healthcare for the part number and pricing for the inlets if they are available.
		09/May/2025 Steve Hardaker
		IHC provided the following part numbers:
		BMBLAS05AS ? Air Inlet.
		BMPRT2004 - O2 Inlet.
		See issue 363930 to SN to add to Intrastats with a price so we can quote.
		22/May/2025 Philip Crossley
		I have added 0332009 BMPRT2004 Blender Oxygen NIST Inlet to the quote for SRN37783 so it can be requested.
		LINKED ISSUE NOTES:
		362598 :
		Added by Aqib Majeed sent to Catherine Spence
		Service Repair Sheet:69099 has been Approved with Customer Order number: RFL626714 SRN37781 Approved SRN37782 Approved SRN37783 Approved
		25 Apr 2025 Catherine Spence
		passed back to engineer

Items for Repair

... ..

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37781	Blender	0310200 Requires Service Manual Linking in System	 2742902	BX1854196	Low Flow Blender	No	No	Unfinished 24 Apr 2025 Philip Crossley	New	00:00
SRN37781 Engineer Notes: INTERNAL NOTES not for customer discussion 24/Apr/2025 Philip Crossley Routine service and calibration test.										
SRN37782	Blender	0310200 Requires Service Manual Linking in System	 2742903	BX1854639	Low Flow Blender	No	No	Unfinished 24 Apr 2025 Philip Crossley	New	00:00