



Carrie Pillow

 CID33476 Opera CID33476 Type:

Carrie Pillow Elker lodge, Moor Lane, Thornton le Clay, York, YO60 7QA, United Kingdom

Tel **07793000070** GBP Retail Price List Vandagraph (0010)

Log Call

Add Issue

Proforma Credit Limit 0.00GBP

 Account
Home

 Main Details

Account Memos

Sales
History

Stock References

 Cust./Supp. Returns

 Service
Visits

Distributor Agreements

Documents
Files

Linked Issues

Regulatory Agreements

SRS69159

SRS Created : 17 Jun 2025

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

Next

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Linked to Order Reference 🔍 **157825**

Service Repair Sheet 69159		Notes
Company / Hospital	Carrie Pillow	17/Jun/2025 Ryan Swaine
Contact Name	Carrie Pillow	17/Jun/2025 Ryan Swaine
Department		TEK-OX sn. TX1521
Position		not turning on, may be battery contact require cleaning. Please repair, check-over and test.
Company Phone	07793000070	
Direct Phone	07793000070	Please pass to MG
Opera Account	CID33476	23/Jun/2025 Robert Connor
Email	Elkerdiving@outlook.com	Received 1 x tek-ox s/n TX1521, with blue tee and hard yellow case.
Order Number		08/Jul/2025 Catherine Spence
Viamed ORD Number		Engineers room
Date Received Into building	23 Jun 2025	
Type	Repair Approved	
Issues?		

Items for Repair										
...										
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37959	Vandagraph Tek Ox	7910211 Requires Service Manual Linking in System	 633068	TX1521	Oxygen Analyser Tek-Ox	No	No	Unfinished 01 Jan 1970		00:00
SRN37959 Engineer Notes: INTERNAL NOTES not for customer discussion 08/Jul/2025 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. All battery contacts and the wiring loom will need to be replaced. The R-17VAN Oxygen sensor has been tested. The sensor has an erratic output when tipped.										

Currently Viewing ITEM SRN37959 Vandagraph Tek Ox 7910211 TX1521 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	08/Jul/2025 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. All battery contacts and the wiring loom will need to be replaced. The R-17VAN Oxygen sensor has been tested. The sensor has an erratic output when tipped.	Non added Yet

ISO REVIEW

Please Select

Instructions