

# Service Repair Sheet SRS69240

Contact Name  
Company/ Hospital Name  
Department  
Position  
Direct Phone  
General Phone  
Opera Account  
Email  
Order Number  
Date Received  
Booked in By  
Main Company  
Type Return

Kumiko Oto  
Ichinen Manufacturing Co., Ltd

00810358250418  
00007696  
tateishi@ichinen.co.jp

24/Sep/2025  
Robert Connor  
Viamed  
Warranty

## VIAMEDclean

**Goods In Only**  
Decontamination  
certificate provided  
by customer

Cleaned by Viamed,  
if no declaration certificate  
from customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

## Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 12/Sep/2025 Steve Nixon

12/Sep/2025 Steve Nixon

Ichinen have already have had 8 x 0110132 R-22AV sensors supplied to them FOC by mistake. They are unable to accept FOC goods. To resolve this they want to return 8 different sensors that are deemed to be faulty. Initially they will return 6 sensors.

24/Sep/2025 Robert Connor

Received 6 x R22AV s/n 212389, 212398, 212405, 222182, 243145, 257497.

After testing, contact CG for serial numbers to assign as replacements, do not replace from stock.

Ready For quote

Repair Complete Signed

CGreen 26.9.25.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38180	Oxygen Sensor	0110132	212389	Yes
SRN38181	Oxygen Sensor	0110132	212398	Yes
SRN38182	Oxygen Sensor	0110132	212405	Yes
SRN38183	Oxygen Sensor	0110132	222182	Yes
SRN38184	Oxygen Sensor	0110132	243145	Yes
SRN38185	Oxygen Sensor	0110132	257497	Yes

0140013 x 6 FOC

S/N, SRS, SRN

0110132 x 6 FOC

New S/N, SRS, SRN

Are No goods sent, as already with customer.

\* EXW - FOC.