

Service Repair Sheet 69240

Contact Name	Kumiko Oto
Company/ Hospital Name	Ichinen Manufacturing Co., Ltd
General Phone	00810358250418
Opera Account	00007696
Email	tateishi@ichinen.co.jp
Date Received	24/Sep/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38180	0110132	212389	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277607

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38181	0110132	212398	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277608

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38182	0110132	212405	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277609

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38183	0110132	222182	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277610

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38184	0110132	243145	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277633

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38185	0110132	257497	Oxygen Sensor	
				Time :0 Hour(s)

Replaced sensor under warranty with S/N 277634
