



The Automation Partnership (Cambridge) Ltd. - Royston

VIAMED LIMITED
15 STATION ROAD
KEIGHLEY
Kent
BD20 7DT

Complaint

First Sample no. / Date

1100105423 / 04.12.2025

Purchasing Document / Item

4561573089 / 00000

Material / description

S-0262 / SENSOR,OXYGEN,MAX-250B_

Document / Version

3717816 / 00

Purchase Qty / Affected Qty

2.000 ST / 2.000 ST

Vendor number / Reference number

999185 /

Inhouse contact / Telephone / Fax

//

Dear sir or madam,

we analyzed the goods delivered by you and discovered the following:

Position 1 Faulty Sensor

The two sensors will not calibrate during set-up.

Serial No LE90799101 and LC77899195

Defect ticket 9265

The Automation Partnership (Cambridge) Ltd.
Royston

The Automation Partnership
(Cambridge) Ltd.
Company Registered Address
Grantham Close
Royston
Hertfordshire SG8 5WY
Phone: +44 1763 227200
Fax: +44 1763 227201
www.automationpartnership.com
www.sartorius-stedim.com

Director:
Dominic Bushnell

Registered in England & Wales
No. 02823205
VAT-ID: GB711570562
WEEE-Registration: WEEE/BG1753ZS
EORI: GB711570562000

HSBC Bank Plc	Sort Code: 40-18-41	SWIFT: HBUKGB4B
GBP Account: 62810786	IBAN: GB19 HBUK 4018 4162 8107 86	
HSBC Bank Plc	Sort Code: 40-12-76	SWIFT: HBUKGB4B
EUR Account: 76164386	IBAN: GB45 HBUK 4012 7676 1643 86	
USD Account: 76164378	IBAN: GB67 HBUK 4012 7676 1643 78	
JPY Account: 76763137	IBAN: GB79 HBUK 4012 7676 7631 37	