



Michael Lamb <viamed.michael.lamb@gmail.com>

Re: Tek-ox o2 sensor

Steve Clay <steve@mikumbadiving.com>
To: ryan.swaine@vandagraph.co.uk

12 December 2025 at 12:47

Hi Ryan,

That would be great thanks.

If not too complicated I'm sure we can do it.

Steve

From: Ryan Swaine <ryan.swaine@vandagraph.co.uk>
Reply to: <ryan.swaine@vandagraph.co.uk>
Date: Friday, 12 December 2025 at 18:37
To: Steve Clay <steve@mikumbadiving.com>
Subject: Re: Tek-ox o2 sensor

Hi Steve

I am sorry it is not so easy for you.

I believe the problem can be solved by changing out the PCB, I can send one to Singapore if you wish.

I have attached some instructions and I would like to know if you are happy to undertake the repair before we do that?

We can provide the parts free of charge, but we would add a £5 value for customs, as they do not accept zero value goods.

I will await your reply.

[Quoted text hidden]

[Quoted text hidden]