

Service Repair Sheet SRS69305

Contact Name
 Company/ Hospital Name
 Department
 Position
 Direct Phone
 General Phone
 Opera Account
 Email
 Order Number
 Date Received
 Booked in By
 Main Company
 Type Return

Sabrina P. Canal Scodino
 Cardiodiagnostico Servicos Medicos

00552734215224
 00552734215224
 CID22465
 adm@cardiodiagnostico.med.br
 09/Dec/2025
 Robert Connor
 Viamed
 Warranty

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	
<input checked="" type="checkbox"/>	
Cleaned by Viamed, if no declaration certificate from customer	
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 2 x 0110081 have failed, s/n 271735 and 271736. Leakage, signs of internal oxidisation. Ryan replied to them and they sent in a report, attached

03/Dec/2025 Kate Griffiths

2 x 0110081 have failed, s/n 271735 and 271736. Leakage, signs of internal oxidisation. Ryan replied to them and they sent in a report, attached - it will need to be translated as necessary. RS says it looks like it IS leaking

09/Dec/2025 Robert Connor

Received 2 x UFO 130-2 s/n 271735, 271736.

INCOTERMS
 DDP

Ready For quote

Repair Complete Signed

Carrie 15.12.25

USD
 End
 User

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38469	Oxygen Sensor	0110081	271735	Yes
SRN38470	Oxygen Sensor	0110081	271736	Yes

01460013 x 2 FOC

old S/N's SRS & SRN's

0110081 x 2 FOC

New S/N's SRS, SRN's

Add ins. to UPS
 label.

(15.12.25.)

PPUFS x 1 23x15x12cm FOC.