

# Work Instructions & Test Methods

## Ventillation Tube Holder

Refer to customers drawing

Select material ,either 5mm Perspex clear castMark position of bends and slots

Using heater and jig bend along drawn line

Smooth all edges with fine emery paper and flame polish

Clean and polish

### QA

Check finished product against customers/master drawing

Check all edges for smoothness

Check that no imperfections are present

Wrap in protective wrapping

