

Service Repair Sheet 69429

Contact Name Matthew Jameson
Company/ Hospital Name Sunderland Royal Hospital
Department Clinical Engineering
Position Senior Clinical Engineering Technician
Direct Phone 01915699933
General Phone 01915656256
Opera Account 00004992
Email matthew.jameson@nhs.net
Order Number RLNP400142411
Date Received 11/May/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38772	0310030	040023	Tom Thumb	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0380000

Tom Thumb TT480 040023 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38773	0310030	040086	Tom Thumb	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0380000

Tom Thumb TT480 040086 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38774	0310030	VMA0081	Tom Thumb	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0380000

Tom Thumb TT480 VMA0081 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38775	0310030	VMI0011	Tom Thumb	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0380000

Tom Thumb TT480 VMI0011 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Service Repair Sheet 69429

Contact Name Matthew Jameson
Company/ Hospital Name Sunderland Royal Hospital
Department Clinical Engineering
Position Senior Clinical Engineering Technician
Direct Phone 01915699933
General Phone 01915656256
Opera Account 00004992
Email matthew.jameson@nhs.net
Order Number RLNP400142411
Date Received 11/May/2026
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38777	0310030	VMC02	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced		Qty: 1	0380000	

Tom Thumb TT480 VMC02 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.
