

Service Repair Sheet 69404

Contact Name	Mr Mahesh Shetty
Company/ Hospital Name	BDI India Private Limited
Department	Customer Support
Position	Sr. Professional Customer Support
Direct Phone	918022560418
General Phone	918022560418
Opera Account	00006454
Email	mahesha@bdi-india.com
Date Received	20/Apr/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38725	1410000	PR02380A12	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		
	Qty: 1	1430320		

V1000 has had transducer and transducer interface cushion replaced, calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38726	1410000	PR02529A11	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		
	Qty: 1	1430277		

V1000 has had transducer interface cushion and battery door replaced, calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38727	1410000	PR02529A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

Service Repair Sheet 69404

Contact Name	Mr Mahesh Shetty
Company/ Hospital Name	BDI India Private Limited
Department	Customer Support
Position	Sr. Professional Customer Support
Direct Phone	918022560418
General Phone	918022560418
Opera Account	00006454
Email	mahesha@bdi-india.com
Date Received	20/Apr/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38728	1410000	PR02529A15	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38729	1410000	PR02529A17	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38730	1410000	PR03143A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		
	Qty: 1	1430288		

This V1000 has serial number PR02529A18 in the battery compartment but internally our original serial number is PR03143A14.

V1000 has had transducer interface cushion and battery contacts replaced, calibration has been checked.

Service Repair Sheet 69404

Contact Name	Mr Mahesh Shetty
Company/ Hospital Name	BDI India Private Limited
Department	Customer Support
Position	Sr. Professional Customer Support
Direct Phone	918022560418
General Phone	918022560418
Opera Account	00006454
Email	mahesha@bdi-india.com
Date Received	20/Apr/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38731	1410000	PR02529A20	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		
	Qty: 1	1430277		

V1000 has had transducer interface cushion and battery door replaced, calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38732	1410000	PR02529A22	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38733	1410000	PR02540A13	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38734	1410000	PR02540A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.
