



Aqib Majeed <viamed.aqib.majeed2@gmail.com>

Fwd: RAV22 sensors

Ryan Swaine <ryan.swaine@viamed.co.uk>

Fri, Jul 31, 2026 at 10:30 AM

Reply-To: ryan.swaine@viamed.co.uk

To: Emily Morton <emily.morton@viamed.co.uk>, Kate Griffiths <kate.griffiths@viamed.co.uk>, Aqib Majeed <aqib.majeed@viamed.co.uk>, Sophie Lines <sophie.lines@viamed.co.uk>

Bcc: viamedinbox@gmail.com

Hi, please process the order for 30x R-22AV (0110132)

Thank you, Ryan

Ryan Swaine

International Sales Manager

VIAMED

www.viamed.co.uk

Email: ryan.swaine@viamed.co.uk

Office: +44 (0) 1535 634542

Mobile: +44 (0) 7803 907117

Check out our product portfolio at:

www.viamed.co.uk/productportfolio

GDPR / Privacy Policy available at www.viamed.co.uk/policy

----- Forwarded message -----

From: **Antti Nurmela** <antti.nurmela@nuvitor.fi>

Date: Fri, 31 Jul 2026 at 10:09

Subject: VS: RAV22 sensors

To: ryan.swaine@viamed.co.uk <ryan.swaine@viamed.co.uk>

Hello,

We could test these. Let's order 30 units.

Terveisin / Best Regards

Antti Nurmela

Nuvitor Oy

Kukonkorventie 9, LT 8

37560 Lempäälä Finland

Puh. / Tel: +358503738808

www.nuvitor.fi

NUVITOR
KORJAAMOLAITEPALVELU

Lähetäjä: Ryan Swaine <ryan.swaine@viamed.co.uk>

Lähetetty: perjantai 31. heinäkuuta 2026 12.03

Vastaanottaja: Antti Nurmela <antti.nurmela@nuvitor.fi>

Aihe: Re: RAV22 sensors

Dear Antti

Thank you for the feedback and I am sorry that you have encountered this issue. Although I am struggling to get my head around what exactly is causing the problem.

I can confirm that we have alternative sensors available, such as the R-22AV from Teledyne:

0110132 Oxygen sensor - Automotive R-22AV

1+ = € 29.50

25+ = € 26.50

Kind regards
Ryan

Ryan Swaine
International Sales Manager
VIAMED
www.viamed.co.uk
Email: ryan.swaine@viamed.co.uk
Office: +44 (0) 1535 634542
Mobile: +44 (0) 7803 907117

Check out our product portfolio at:
www.viamed.co.uk/productportfolio

GDPR / Privacy Policy available at www.viamed.co.uk/policy

On Fri, 31 Jul 2026 at 08:43, Antti Nurmela <antti.nurmela@nuvitor.fi> wrote:

Hello Ryan,

I haven't gotten around to sending the faulty sensors back to you. In my opinion, many of the other sensors show a similar issue as well, so it may simply be a characteristic of this sensor.

Unfortunately, a competitor's (Citytech's) sensor performs better. Do you have any other sensor models available that might work better in our application?

Additionally, I have noticed that the threaded section of the Citytech sensor is slightly thicker than that of your sensor. A thicker threaded section would also be a better fit for our application.

Terveisin / Best Regards
Antti Nurmela
Nuvitor Oy
Kukonkorventie 9, LT 8
37560 Lempäälä Finland
Puh. / Tel: +358503738808
www.nuvitor.fi

NUVITOR
KORJAAMOLAITEPALVELU