

Norman Atkins Gas Safety Record

Landlords Address

Via Med
15 Station Road, Crosshills, KEIGHLEY,
WEST YORKSHIRE
BD20 7DT
United Kingdom
Customer ID: 5145

NORMAN ATKINS P & H LTD
1 Greengate Road, Keighley, West Yorkshire
BD21 5LH
Phone: 01535 603893
Fax: 01535 691166



935

Date Received: 24/07/2026 Completion Time 10/08/2026 P.O. Number: **Certificate No: LC-5145/57779**
Date Attended: 10/08/2026 Job Status: Completed Engineer: Nick Hollings Registered ID: 6004800 Workorder ID: 57779

Appliance and Inspection Details

App ID	Room	Type	Make/Model	App. Owner	Flue Type	Inlet Pres. mBar	Opr. Press. or Heat Input	Safety Device Correct Op. Yes/No/Na	Ventilation Adequate Yes/No/Na	Flue Flow Test Pass/Fail/Na	Flue Spillage Test Pass/Fail/Na	Termination Satisfactory Yes/No/Na	Flue Visual Condition Pass/Fail/Na	CO Hi ppm Lo ppm	CO2 Hi % Lo %	CO/CO2 Hi Ratio Lo Ratio	Serviced Yes/No/Installed	Inspected Yes/No	Safe to use Yes/No
7610	Warehouse	BOILER	Worcester Greenstar 40 CDI Conventional	Oc	RS	19	40.0 kWh	Yes	n/a	n/a	n/a	Yes	Pass	97 31	9.7 8.9	0.0010 0.0003	Yes	Yes	Yes
7612	Warehouse	Multi Point Wtr Htr	Chaffateaux Britony 2T	Oc	RS	17	9.0 mBar	Yes	n/a	n/a	n/a	Yes	Pass	n/a n/a	n/a n/a	n/a n/a	Yes	Yes	Yes
10338	LANDING	Combi Boiler	Ideal logic max combi 2 30kw	Oc	RS	19	28.0 kWh	Yes	n/a	n/a	n/a	Yes	Pass	132 63	9.4 8.8	0.0014 0.0007	Yes	Yes	Yes

Notes

	Defects Identified	Remedial Action Taken	Warning/Advice Notice No
7612	Flue was dented.	Terminal guard fitted already.	No
10338	All ok.		

Gas Pipework Visual Inspection Satisfactory	Yes	Emergency Control Valve Accessible	Yes	Gas Tightness Satisfactory	NA	Earth Bonding Satisfactory	Yes	System Inhibitor	NA	NA
---	-----	------------------------------------	-----	----------------------------	----	----------------------------	-----	------------------	----	----

Unsafe Situation Identified

This inspection is for gas safety purpose only in accordance with the current Gas Safety (Installation and Use) Regulations. Chimney Systems/Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed inspection of the Flue integrity, construction and lining has not been carried out. This is not a guarantee of the reliability of the appliance.

Appliances recorded: 3 Serviced: 3 Inspected: 3

This safety record is issued by: Nick Hollings

Date: 10/08/2026

I confirm that the work was carried out to my satisfaction, free from damage to fixtures and fittings: HELEN. LAMB

NH
NH

NEXT SERVICE DUE BY
10/08/2027