

Service Repair Sheet 69478

Contact Name	Matthew Jameson
Company/ Hospital Name	Sunderland Royal Hospital
Department	Clinical Engineering
Position	Senior Clinical Engineering Technician
Direct Phone	01915699933
General Phone	01915656256
Opera Account	00004992
Email	matthew.jameson@nhs.net
Order Number	RLNP400147021
Date Received	03/Aug/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38971	0310030	040024	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 040024 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38972	0310030	040027	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		
	Qty: 1	0330212		
	Qty: 1	0330203		

Tom Thumb TT480 040027 has been stripped and cleaned then reassembled with new O rings and a new gauge. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38973	0310030	040092	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		
	Qty: 1	0330236		

Tom Thumb TT480 040092 has been stripped and cleaned then reassembled with new O rings and a new gauge face. The two valves have been checked and reset before QA.

Service Repair Sheet 69478

Contact Name	Matthew Jameson
Company/ Hospital Name	Sunderland Royal Hospital
Department	Clinical Engineering
Position	Senior Clinical Engineering Technician
Direct Phone	01915699933
General Phone	01915656256
Opera Account	00004992
Email	matthew.jameson@nhs.net
Order Number	RLNP400147021
Date Received	03/Aug/2026
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38974	0310030	VMC9068	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMC9068 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair	Ref	S/N	Equipment Type	
SRN38975	0310030	VMI0014	Tom Thumb	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0380000		

Tom Thumb TT480 VMI0014 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.
