

Oxygen Tents/Hoods Tanda

Enclosures to enable oxygen enriched air and humidity to be supplied to the patients head only

> Class IIa Via Rule Rule 2 Assesment Route Annex II NBOG MD 0100

Carried out by Derek Lamb 25 / 10 / 18



- Stock References Review
- Supplier Review
- Sales Review
- Countries Review
- Returns Review
- Design Changes Review
- User Instructions Review
- Labels Review
- Document Updates Review
- Internal Issues Review
 - Clinical / FDA Incidents online search

Stock References Review

| Stock Reference | Description |
|-----------------|--|
| PP1968 | |
| | Connector - 22mm Oxygen Stem. |
| PP8000 | Oxygen Hood - Size 1 with sliding front |
| PP8000/SF | Sliding Front for use with PP8000/PP8020 |
| PP8020 | Oxygen Hood - Size 1 with sliding front |
| PP8050 | Oxygen Hood - Size 2 with sliding front |
| PP8050/SF | Sliding Front for use with PP8050/PP8055 |
| PP8055 | Oxygen Hood - Size 2 with sliding front |
| PP8060 | Oxygen Hood - Size 3 with sliding front |
| PP8060/SF | Sliding Front for use with PP8060/PP8065 |
| PP8065 | Oxygen Hood - Size 3 with sliding front |
| PP8066 | Sliding Front Retaining Knob |
| PP8509 | Phototherapy Light Shield/Oxygen Hood. |
| PP8533 | Phototherapy Light Shield/Oxygen Hood. |
| PP8540 | Phototherapy Light Shield/Oxygen Hood. |
| PP8562 | Phototherapy Light Shield/Oxygen Hood. |
| PP8565 | Phototherapy Light Shield/Oxygen Hood. |
| PP8589 | Oxygen Hood - Size 4 with sliding front |
| PP8589/SF | Sliding Front for use with PP8589/PP8715 |
| PP8591 | Special Made To Customer Spec |
| PP8593 | Oxygen headbox made to customer`s |
| PP85XX | Special Made to Cusomer Spec |
| PP8687 | Oxygen hood - special. With side doors. |
| PP8715 | Oxygen Hood - Size 4 with sliding front |
| PP8729 | Oxygen hood - special. |
| PP8730 | Oxygen hood - special. |
| PP8744 | Oxygen hood - special. |
| PP8746 | Oxygen hood - special. |
| PP8747 | Oxygen hood - special. |
| PP8748 | Oxygen hood - special. |
| PP8752 | Oxygen hood - special. |
| PP8753 | Oxygen hood - special. |
| PP8754 | Oxygen hood - special. |
| PP8755 | Oxygen hood - special. |
| PP8756 | Oxygen hood - special. |
| PP8757 | Oxygen hood - special. |
| PP8758 | Oxygen hood - special. |
| PP8759 | Oxygen hood - special. |
| PP8760 | Oxygen hood - special. |
| PP8771 | Oxygen Hood - Special |
| PP8772 | Oxygen hood - special. |
| PP8773 | Oxygen hood - special. |
| PP8774 | Oxygen Hood - special. |
| . 1 01/1 | on gon nood openial. |

| Stock Reference | Description |
|-----------------|--------------------------------------|
| PP8775 | Oxygen Hood - special. |
| PP8780 | Oxygen Hood - Size 1 without sliding |
| PP8781 | Oxygen Hood - Size 2 without sliding |
| PP8782 | Oxygen Hood - Size 3 without sliding |
| PP8783 | Oxygen Hood - Size 1 without sliding |
| PP8784 | Oxygen Hood - Size 2 without sliding |
| PP8785 | Oxygen Hood - Size 3 without sliding |
| PP8791 | Oxygen Hood - Special |

Comments on Stock references review:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Supplier Review

| Stock Ref. | Description | Supplier A/C | Supplier P/N | Supplier Name | Rating |
|------------|--------------------------|--------------|--------------|-----------------------|--------|
| PP8000 | Oxygen Hood - Size 1 wi | 00009022 | PP8000 | Tanda Engineering Ltd | В |
| PP8020 | Oxygen Hood - Size 1 wi | 00009022 | PP8020 | Tanda Engineering Ltd | В |
| PP8050 | Oxygen Hood - Size 2 wi | 00009022 | PP8050 | Tanda Engineering Ltd | В |
| PP8050/SF | Sliding Front for use wi | 00009022 | PP8050/SF | Tanda Engineering Ltd | В |
| PP8055 | Oxygen Hood - Size 2 wi | 00009022 | PP8055 | Tanda Engineering Ltd | В |
| PP8060 | Oxygen Hood - Size 3 wi | 00009022 | PP8060 | Tanda Engineering Ltd | В |
| PP8065 | Oxygen Hood - Size 3 wi | 00009022 | PP8065 | Tanda Engineering Ltd | В |
| PP8066 | Sliding Front Retaining | 00009022 | | Tanda Engineering Ltd | В |
| PP8509 | Phototherapy Light Shiel | 00009022 | PP8509 | Tanda Engineering Ltd | В |
| PP8533 | Phototherapy Light Shiel | 00009022 | PP8533 | Tanda Engineering Ltd | В |
| PP8562 | Phototherapy Light Shiel | 00009022 | PP8060/A | Tanda Engineering Ltd | В |
| PP8589 | Oxygen Hood - Size 4 wi | 00009022 | PP8589 | Tanda Engineering Ltd | В |
| PP8593 | Oxygen headbox made to c | 00009022 | PP8593 | Tanda Engineering Ltd | В |
| PP8687 | Oxygen hood - special. | 00009022 | PP8687 | Tanda Engineering Ltd | В |
| PP8715 | Oxygen Hood - Size 4 wi | 00009022 | PP8715 | Tanda Engineering Ltd | В |
| PP8729 | Oxygen hood - special. | 00009022 | PP8729 | Tanda Engineering Ltd | В |
| PP8730 | Oxygen hood - special. | 00009022 | PP8730 | Tanda Engineering Ltd | В |
| PP8744 | Oxygen hood - special. | 00009022 | PP8744 | Tanda Engineering Ltd | В |
| PP8746 | Oxygen hood - special. | 00009022 | PP8746 | Tanda Engineering Ltd | В |
| PP8747 | Oxygen hood - special. | 00009022 | PP8747 | Tanda Engineering Ltd | В |
| PP8748 | Oxygen hood - special. | 00009022 | PP8748 | Tanda Engineering Ltd | В |
| PP8754 | Oxygen hood - special. | 00009022 | PP8754 | Tanda Engineering Ltd | В |
| PP8755 | Oxygen hood - special. | 00009022 | PP8755 | Tanda Engineering Ltd | В |
| PP8756 | Oxygen hood - special. | 00009022 | PP8756 | Tanda Engineering Ltd | В |
| PP8757 | Oxygen hood - special. | 00009022 | PP8757 | Tanda Engineering Ltd | В |
| PP8758 | Oxygen hood - special. | 00009022 | PP8758 | Tanda Engineering Ltd | В |
| PP8759 | Oxygen hood - special. | 00009022 | PP8759 | Tanda Engineering Ltd | В |
| PP8760 | Oxygen hood - special. | 00009022 | PP8760 | Tanda Engineering Ltd | В |
| PP8771 | Oxygen Hood - Special | 00009022 | PP8771 | Tanda Engineering Ltd | В |
| PP8774 | Oxygen Hood - special. | 00009022 | PP8774 | Tanda Engineering Ltd | В |
| PP8775 | Oxygen Hood - special. | 00009022 | PP8775 | Tanda Engineering Ltd | В |
| PP8781 | Oxygen Hood - Size 2 wi | 00009022 | | Tanda Engineering Ltd | В |
| PP8782 | Oxygen Hood - Size 3 wi | 00009022 | | Tanda Engineering Ltd | В |
| PP8791 | Oxygen Hood - Special | 00009022 | PP8791 | Tanda Engineering Ltd | В |
| PP1968 | Connector - 22mm Oxygen | 00009082 | 1968000 | Intersurgical Ltd | В |

Comments on Suppliers:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Sales Information

| Stock Reference | Description | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 |
|-----------------|--|------|------|------|------|------|------|------|
| PP1968 | Connector - 22mm Oxygen | 48 | 172 | 35 | 151 | 16 | 30 | |
| PP8000 | Oxygen Hood - Size 1 wi | 14 | 9 | 38 | 13 | 10 | 9 | |
| PP8000/SF | Sliding Front for use with PP8000/PP8020 | | | | | | | |
| PP8020 | Oxygen Hood - Size 1 wi | | 1 | 13 | 18 | 5 | 2 | |
| PP8050 | Oxygen Hood - Size 2 wi | 98 | 8 | 39 | 16 | 15 | 4 | |
| PP8050/SF | Sliding Front for use wi | | 1 | | | | | |
| PP8055 | Oxygen Hood - Size 2 wi | 1 | 12 | 7 | 4 | 10 | | |
| PP8060 | Oxygen Hood - Size 3 wi | 27 | 21 | 22 | 28 | 25 | 5 | 11 |
| PP8060/SF | Sliding Front for use with PP8060/PP8065 | | | | | | | |
| PP8065 | Oxygen Hood - Size 3 wi | 14 | 9 | 8 | 7 | 9 | 3 | |
| PP8066 | Sliding Front Retaining | | 2 | 2 | | | | |
| PP8509 | Phototherapy Light Shiel | | 1 | | | | | |
| PP8533 | Phototherapy Light Shiel | | 20 | 81 | 22 | 30 | 70 | |
| PP8540 | Phototherapy Light Shield/Oxygen Hood. | | | | | | | |
| PP8562 | Phototherapy Light Shiel | 1 | | | 4 | | | |
| PP8565 | Phototherapy Light Shield/Oxygen Hood. | | | | | | | |
| PP8589 | Oxygen Hood - Size 4 wi | 24 | 33 | 30 | 25 | 15 | 3 | 13 |
| PP8589/SF | Sliding Front for use with PP8589/PP8715 | | | | | | | |
| PP8591 | Special Made To Customer Spec | | | | | | | |
| PP8593 | Oxygen headbox made to c | | | | | | | |
| PP85XX | Special Made to Cusomer Spec | | | | | | | |
| PP8687 | Oxygen hood - special. | 2 | | | | | | |
| PP8715 | Oxygen Hood - Size 4 wi | 2 | 12 | 7 | 4 | 1 | 2 | |
| PP8729 | Oxygen hood - special. | | | | | | | |
| PP8730 | Oxygen hood - special. | | | | | | | |
| PP8744 | Oxygen hood - special. | | | | | | | |
| PP8746 | Oxygen hood - special. | | | | | | | |
| PP8747 | Oxygen hood - special. | | | | | | | |
| PP8748 | Oxygen hood - special. | | | | | | | |
| PP8752 | Oxygen hood - special. | | | | | | | |
| PP8753 | Oxygen hood - special. | | | | | | | |
| PP8754 | Oxygen hood - special. | | | | | | | |
| PP8755 | Oxygen hood - special. | | | | | | | |
| PP8756 | Oxygen hood - special. | | | | | | | |
| PP8757 | Oxygen hood - special. | | | | | | | |
| PP8758 | Oxygen hood - special. | | | | | | | |
| PP8759 | Oxygen hood - special. | | | | | | | |
| PP8760 | Oxygen hood - special. | | | | | | | |
| PP8771 | Oxygen Hood - Special | | 3 | 3 | | | | |
| PP8772 | Oxygen hood - special. | | | | | | | |
| PP8773 | Oxygen hood - special. | | | | | | | |
| PP8774 | Oxygen Hood - special. | 2 | | | | | | |

| Stock Reference | Description | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 |
|-----------------|--------------------------------------|------|------|------|------|------|------|------|
| PP8775 | Oxygen Hood - special. | | | | | | | |
| PP8780 | Oxygen Hood - Size 1 without sliding | | | | | | | |
| PP8781 | Oxygen Hood - Size 2 wi | | 5 | | | | | |
| PP8782 | Oxygen Hood - Size 3 wi | | 5 | | | | | |
| PP8783 | Oxygen Hood - Size 1 without sliding | | | | | | | |
| PP8784 | Oxygen Hood - Size 2 without sliding | | | | | | | |
| PP8785 | Oxygen Hood - Size 3 without sliding | | | | | | | |
| PP8791 | Oxygen Hood - Special | | | | 2 | | | |

Comments on Sales Information:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Countries Review

| Country | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 |
|------------------------|------|------|------|------|------|------|------|
| AU Austria | | | [X] | | | | |
| B Belgium | [X] | [X] | [X] | [X] | [X] | [X] | |
| BA Kingdom of Bahrain | [X] | | | [X] | | | |
| BO Bosnia | | | | [X] | | | |
| CHA Channel Islands | | | | | | | |
| CY Cyprus | | | | [X] | [X] | | |
| EC Ecuador | | | [X] | | | | |
| F France | [X] | | | [X] | [X] | | |
| GI Gibraltar | | [X] | | | | | |
| GR Greece | | | [X] | | | | |
| IN India | | [X] | | | | | |
| IRE Ireland | [X] | [X] | [X] | [X] | [X] | | |
| IT Italy | | | | | | | |
| JO Jordan | | | | | | | |
| KU Kuwait | | | | [X] | | | |
| MA Malaysia | | | | | | | |
| MAC Macedonia | | [X] | | [X] | | | |
| MAU Mauritius | | | | | [X] | [X] | |
| MO Morrocco | | | | | | | |
| MOL MOLDOVA | | [X] | [X] | | | | |
| NE Netherlands | | | | | | | |
| NI Northern Ireland | [X] | [X] | | | | | |
| OM Oman | [X] | [X] | [X] | [X] | [X] | [X] | |
| P Poland | | [X] | | | | | |
| PO Portugal | | | | [X] | | | |
| Q Qatar | [X] | | | | | | |
| RO Romania | | | | [X] | [X] | | [X] |
| RU Russia | | [X] | [X] | [X] | [X] | [X] | |
| SC Scotland | [X] | | [X] | | | | |
| SP Spain | [X] | [X] | | | [X] | [X] | [X] |
| SW Sweden | | | | | | | |
| T Turkey | | | | | | | |
| TT Trinidad and Tobago | | [X] | | | | | |
| UAE U A E | | [X] | | | | | |
| UK United Kingdom | [X] | [X] | [X] | [X] | [X] | [X] | |
| YE Yemen | | | [X] | | | | |

Comments on Sales to Countries:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks with Sales to Countries:

Returns and Q.A. Fails Review

| Stock Reference | Fault | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 |
|-----------------|-------------------------------|------|------|------|------|------|------|------|
| PP8050 | Unchecked - Returned To Stock | | | 1 | | | | |
| PP8055 | New | | | | | | | |
| PP8060 | Unchecked - Returned To Stock | | | | | | | |
| PP8533 | No Fault Found | | | 1 | | | | |
| PP8533 | Unchecked - Returned To Stock | | | | | | 1 | |
| PP8589 | Hair Line Crack | | | | | | 2 | |
| PP8715 | New | | | | | | | |
| PP8715 | Unchecked - Returned To Stock | | | | | | | |
| PP8757 | No Fault Return To Stock | | | | | | | |
| PP8758 | No Fault Return To Stock | | | | | | | |

Comments on Returns:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks with Returns and Potential Re-work:

Design Changes Review

Showing Documents Filed in Y 14 Design Changes

Comments on Design Changes:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks with Design Changes:

User Instructions Review

Showing Documents Filed in F 5 User Instructions

| Document ID | Description | Date Added/Updated |
|-------------|---|--------------------|
| 14778 | Oxygen Hoods Instructions for Use User Manual | 19/02/15 |

Comments on User Instructions:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks User Instructions:

Labels Review

Showing Documents Filed in F7/F8 Labels

| Document ID | Description | Date Added/Updated |
|-------------|------------------------------|--------------------|
| 16792 | Head Box Oxygen Hoods Labels | 20/04/16 |
| 9526 | Oxygen Hoods Labels 0430011 | 18/10/11 |
| 9169 | No accessory labels | 18/10/11 |
| 8523 | Oxygen Hoods Labels | 13/07/11 |
| 8521 | Oxygen Hoods Labels 0430010 | 13/07/11 |

Comments on Labels:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks Labels:

Documentation Updates / Changes

| Document ID | Description | Date Added/Updated |
|-------------|--|--------------------|
| 24894 | Oxygen Tents/Hoods Tanda Clinical Trials Reports papers | 17/01/18 |
| 24639 | Oxygen Tents/Hoods Tanda Clinical evaluation | 12/12/17 |
| 23878 | Oxygen Tents/Hoods Tanda Design Input Device Design Theory Oxy | 13/11/17 |
| 22393 | Oxygen Hoods Clinical Trials Reports Reviews and Post Market Sur | 02/10/17 |

Comments on Document Changes:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks with Document Changes:

Internal Issues Review Number of Issues reviewed: 19

| Issue ID | Subject |
|----------|--|
| | - |
| 107589 | Office Meeting Sales Back Orders Review - By Customer Backorder 00000450 PP8050 ORD89232 |
| 107590 | Office Meeting Sales Back Orders Review - By Customer Backorder 00000450 PP8060 ORD89233 |
| 108440 | Office Meeting Sales Back Orders Review - By Customer Backorder 00000620 PP8065 ORD89413 |
| 104555 | Office Meeting Sales Back Orders Review - By Customer Backorder 00001310 PP8000 ORD88632 |
| 108233 | Office Meeting Sales Back Orders Review - By Customer Backorder 00005117 PP8589 ORD89377 |
| 108511 | Office Meeting Sales Back Orders Review - By Customer Backorder 00006304 PP8060 ORD89378 |
| 105321 | Office Meeting Sales Back Orders Review - By Customer Backorder 00007029 PP8000 ORD88793 |
| 109343 | Office Meeting Sales Back Orders Review - By Customer Backorder 00007273 PP8533 ORD89109 |
| 106398 | Office Meeting Stock Processing EAN code mismatch |
| 107518 | Office Meeting Stock Processing Pallet dims |
| 105619 | Office Meeting Back Order Report POR11477 PP8000 // |
| 105623 | Office Meeting Back Order Report POR11478 PP1968 // |
| 107344 | Office Meeting Back Order Report POR11500 PP8533 // |
| 107690 | Office Meeting Back Order Report POR11515 PP1968 // |
| 110475 | Office Meeting Back Order Report POR11518 PP8050 // |
| 110468 | Office Meeting Back Order Report POR11518 PP8050 // |
| 108706 | Office Meeting Back Order Report POR11529 PP8060 // |
| 108707 | Office Meeting Back Order Report POR11529 PP8065 // |
| 105107 | Office Meeting Stock Processing Warehouse Request |

Comments on Issues:

we have ceased selling these devices due to MHRA / BSI regulations and costs

Comments on Risks with Issues:

Backorder 00000450 PP8050 ORD89232

Issue ID #107589

Date Created 08/Nov/2017

Issued To: General

Completed Status: 28 Dec 2017

Stock Ref: PP8050 Opera A/c: 00000450

Order Number: ORD89232

Notes:

08 Nov 2017 09:07:41 AM Zoey Teal Advised £20 carriage charge

21 Nov 2017 07:54:17 AM Catherine Spence Back Order - Supplier

30 Nov 2017 09:17:50 AM Zoey Teal Advised lead time

28 Dec 2017 08:19:01 AM Catherine Spence Shipping Thu 28 Dec 2017

Backorder 00000450 PP8060 ORD89233

Issue ID #107590

Date Created 08/Nov/2017

Issued To: General

Completed Status: 09 Nov 2017

Stock Ref: PP8060 Opera A/c: 00000450

Order Number: ORD89233

Notes:

08 Nov 2017 09:07:49 AM Zoey Teal Advised £20 carriage charge

Backorder 00000620 PP8065 ORD89413

Issue ID #108440

Date Created 17/Nov/2017

Issued To: General

Completed Status: 28 Dec 2017

Stock Ref: PP8065 Opera A/c: 00000620

Order Number: ORD89413

Notes:

17 Nov 2017 04:50:09 PM Sophie Lines Incorrect price. Awaiting response from Ali Hasan - he has emailed end user but hasn't come back yet

Backorder 00001310 PP8000 ORD88632

Issue ID #104555

Date Created 04/Oct/2017

Issued To: General

Completed Status: 06 Oct 2017

Stock Ref: PP8000 Opera A/c: 00001310

Order Number: ORD88632

Notes:

04 Oct 2017 11:50:34 AM Emily Hanson emailed about wrong price/carriage

05 Oct 2017 09:15:12 AM Emily Hanson okay to fo

Backorder 00005117 PP8589 ORD89377

Issue ID #108233

Date Created 15/Nov/2017

Issued To: General

Completed Status: 16 Nov 2017

Stock Ref: PP8589 Opera A/c: 00005117

Order Number: ORD89377

Notes:

15 Nov 2017 03:06:54 PM Emily Hanson okay to gogog

Backorder 00006304 PP8060 ORD89378

Issue ID #108511

Date Created 20/Nov/2017

Issued To: General

Completed Status: 03 Jan 2018

Stock Ref: PP8060 Opera A/c: 00006304

Order Number: ORD89378

Notes:

20 Nov 2017 08:16:52 AM Catherine Spence Back Order - Supplier

30 Nov 2017 08:41:44 AM Zoey Teal Aware of lead time.

Backorder 00007029 PP8000 ORD88793

Issue ID #105321

Date Created 13/Oct/2017

Issued To: General

Completed Status: 23 Nov 2017

Stock Ref: PP8000 Opera A/c: 00007029

Order Number: ORD88793

Notes:

13 Oct 2017 08:28:39 AM Catherine Spence Back Order - Supplier

02 Nov 2017 02:03:54 PM Sarah Walton See Attached Notes Customer aware of the lead time.

06 Nov 2017 07:58:42 AM Catherine Spence Back Order - Supplier

Backorder 00007273 PP8533 ORD89109

Issue ID #109343

Date Created 29/Nov/2017

Issued To: General

Completed Status: 05 Dec 2017

Stock Ref: PP8533 Opera A/c: 00007273

Order Number: ORD89109

Notes:

29 Nov 2017 03:19:55 PM Katie Evans See Attached Notes Aware of lead time

29 Nov 2017 03:20:06 PM Katie Evans Part shipped 28/11/2017

05 Dec 2017 10:31:07 AM Katie Evans Moved to PRO04751 as per customer request

VIAMED Stock Meeting - Stock Processing

EAN code mismatch

Issue ID #106398

Date Created 24/Oct/2017

Issued To: Derek Lamb

Completed Status: 24 Oct 2017

Notes:

Added by Robert Connor sent to Derek Lamb
INFORMATION ONLY ISSUE DO NOT ADD NOTES!
PP1968 - oxygen stem. EAN code does not match that from supplier, should be 5030267057511

VIAMED Stock Meeting - Stock Processing

Pallet dims

Issue ID #107518

Date Created 07/Nov/2017 Issued To: Sarah Walton

Completed Status: 09 Nov 2017

Notes:

Added by Jonathan Connor sent to Sarah Walton Artisans. 10 * PP8060 and 13*PP8589

2 pallets. Each would be 1.2*1*1.6(height) m

09 Nov 2017 Sarah Walton Done, thanks

09 Nov 2017 Jonathan Connor thanks

POR11477 PP8000 //

Issue ID #105619

Date Created 17/Oct/2017 Issued To: Jonathan Connor Completed Status: 17 Oct 2017

Notes:

POR11477 PP8000 Estimated ship to us date changed to //

POR11478 PP1968 //

Issue ID #105623

Date Created 17/Oct/2017 Issued To: Jonathan Connor Completed Status: 18 Oct 2017

Notes:

POR11478 PP1968 Estimated ship to us date changed to //

POR11500 PP8533 //

Issue ID #107344

Date Created 06/Nov/2017 Issued To: Jonathan Connor Completed Status: 06 Nov 2017

Notes:

POR11500 PP8533 Estimated ship to us date changed to //

POR11515 PP1968 //

Issue ID #107690

Date Created 09/Nov/2017 Issued To: Jonathan Connor Completed Status: 10 Nov 2017

Notes:

POR11515 PP1968 Estimated ship to us date changed to //

POR11518 PP8050 //

Issue ID #110475

Date Created 15/Dec/2017 Issued To: Jonathan Connor Completed Status: 15 Dec 2017

Notes:

POR11518 PP8050 Estimated ship to us date changed to //

POR11518 PP8050 //

Issue ID #110468

Date Created 15/Dec/2017 Issued To: Jonathan Connor Completed Status: 15 Dec 2017

Notes:

POR11518 PP8050 Estimated ship to us date changed to //

POR11529 PP8060 //

Issue ID #108706

Date Created 22/Nov/2017 Issued To: Jonathan Connor Completed Status: 23 Nov 2017

Notes:

POR11529 PP8060 Estimated ship to us date changed to //

POR11529 PP8065 //

Issue ID #108707

Date Created 22/Nov/2017 Issued To: Jonathan Connor Completed Status: 23 Nov 2017

Notes:

POR11529 PP8065 Estimated ship to us date changed to //

Stock Processing - Stock Processing

Warehouse Request

Issue ID #105107

Date Created 11/Oct/2017 Issued To: Jonathan Connor Completed Status: 14 Nov 2017

Notes:

Side Port for use with PP8715 Oxygen

11 Oct 2017 Jonathan Connor Thanks

Clinical / FDA Incidents online search

Clinical Investigation online review

Do any of the Results indicate a Risk / Problem : No Do any of the Results indicate outdated Technology : No Comments on Clinical Search :

we have ceased selling these devices due to MHRA / BSI regulations and costs

Review of online FDA Incident reports

Do any of the Results indicate a Risk / Problem: No Do any of the Results indicate outdated Technology: No Comments on Clinical Search:

we have ceased selling these devices due to MHRA / BSI regulations and costs