

Return sensor List

###

1	SOX-N1A	I8	A209029	over shoot fail
2	SOX-N1A	I8	A209038	over shoot fail
3	SOX-N1A	I8	A209043	over shoot fail
4	SOX-N1A	I8	A209048	over shoot fail
5	SOX-N1A	I8	A209056	over shoot fail
6	SOX-N1A	I8	A209060	over shoot fail
7	SOX-N1A	I8	A209062	over shoot fail
8	SOX-N1A	I8	A209063	over shoot fail
9	SOX-N1A	I8	A209065	over shoot fail
10	SOX-N1A	I8	A209073	over shoot fail
11	SOX-N1A	I8	A209077	Responsibility
12	SOX-N1A	I8	A209082	over shoot fail

1	SOX-N1A	I8	A209091	over shoot fail
2	SOX-N1A	I8	A209092	over shoot fail
3	SOX-N1A	I8	A209095	over shoot fail
4	SOX-N1A	I8	A209096	over shoot fail
5	SOX-N1A	I8	A209097	over shoot fail
6	SOX-N1A	I8	A209100	over shoot fail
7	SOX-N1A	I8	A209101	over shoot fail
8	SOX-N1A	I8	A209103	over shoot fail
9	SOX-N1A	I8	A209104	over shoot fail
10	SOX-N1A	I8	A209106	over shoot fail
11	SOX-N1A	I8	A209107	over shoot fail
12	SOX-N1A	I8	A209109	over shoot fail
13	SOX-N1A	I8	A209117	over shoot fail
14	SOX-N1A	I8	A209121	over shoot fail
15	SOX-N1A	I8	A209123	over shoot fail
16	SOX-N1A	I8	A209132	over shoot fail
17	SOX-N1A	I8	A209133	over shoot fail
18	SOX-N1A	I8	A209141	over shoot fail
19	SOX-N1A	I8	A209144	over shoot fail
20	SOX-N1A	I8	A209145	over shoot fail
21	SOX-N1A	I8	A209146	over shoot fail
22	SOX-N1A	I8	A209148	over shoot fail
23	SOX-N1A	I8	A209200	abnormal output
24	SOX-N1A	I8	A209208	abnormal output
25	SOX-N1A	I8	A209212	abnormal output
26	SOX-N1A	I8	A209243	abnormal output

1	R22AV	G8	181178	abnormal output
---	-------	----	--------	-----------------