

Steve

AGGAR LABELS

4/2/03

It would seem that the problems with fitting the labels has been a combination of things. There is a variance in the surface DIMENSIONS in the 3 SAMPLE timers and the same problem with the labels.

I have made a note of the DIMENSIONS and placed them with the respective SAMPLE so you can see the difference.

I have took it upon myself to measure and cut out a sample of my own that fits all three samples (please excuse the crudity). Hopefully this will solve the big problems we have been having and can we try we use a thicker plastic, this needs to be done mainly on the top bar under the reset switch.

Using a thicker plastic will stop any imperfections caused by the nut holding the Button in place.

If you have any more queries let me know.
Many thanks

MARK.

Two sample was back
made looking into account
the variables in the measurement
of the timer & FITS
ALL 3 SAMPLE
TIMERS.



SAMPLE 3.

85.90 $\leftrightarrow$

53.37 $\uparrow$

57.24 $\leftrightarrow$ BOTTOM 4.45 $\leftrightarrow$

32.05 $\uparrow$ BOTTOM 9.02 $\downarrow$

21.25 $\downarrow$ BOTTOM.

SAMPLE 2.

$\leftrightarrow$ = 85.94 $\uparrow$ = 53.39.

57.26 $\leftrightarrow$ TO BOTTOM 9.47

32.09 $\downarrow$ TO BOTTOM. 9.98.

21.27 $\downarrow$ BOTTOM.

SAMPLE 1

86.07 $\leftrightarrow$

53.46 $\uparrow$

57.38 $\leftrightarrow$ BOTTOM 9.47.

32.12 $\uparrow$ BOTTOM 9.03.

21.31 $\downarrow$