



Sarah Walton <viamed.sarah.walton@gmail.com>

SRS67567 oxygen sensor returns status

1 message

Steve Nixon <office@viamed.co.uk>

29 September 2020 at 10:46

Reply-To: steve.nixon@vandagraphst.com

To: Jim McKay <J.McKay@jfdglobal.com>

Cc: Shaun McGarva <S.McGarva@jfdglobal.com>, Duncan Clark <D.Clark@jfdglobal.com>, Sarah Walton <sarah.walton@vandagraphst.com>

Good morning

The status of the oxygen sensor returns is as follows:

We will generate a FOC order to cover the following 14 sensors:

SRS67567JFD returned 14 sensors 18th August

SN	SRS	SRN	
101156	SRS67567	SRN33009	To be replaced
101159	SRS67567	SRN33010	To be replaced
101162	SRS67567	SRN33011	To be replaced
101163	SRS67567	SRN33012	To be replaced
101166	SRS67567	SRN33013	To be replaced
101167	SRS67567	SRN33014	To be replaced
101176	SRS67567	SRN33015	To be replaced
101221	SRS67567	SRN33016	To be replaced
101255	SRS67567	SRN33017	To be replaced
101256	SRS67567	SRN33018	To be replaced
101274	SRS67567	SRN33019	To be replaced
101487	SRS67567	SRN33020	To be replaced
101581	SRS67567	SRN33021	To be replaced
101582	SRS67567	SRN33022	To be replaced

Regards

--

Steve

Steve Nixon
Director - Vandagraph Sensor Technologies Ltd.

Office: +44 (0)1535 634900
Mobile: +44 (0)7850 252267